

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT123001634/SVP3E2**Date:** 25/07/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00063362202	
Claimant Vehicle No :	GBL6380B	Insured Vehicle No :	GBL1668E	
Date of Loss:	02/02/2023	Nature of Claim:	TP	Claim No: SNM23D200901/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL6380B		Engine No:	QR20020258R
Make & Model:	NISSAN NV350 CARAVAN, 2.0 DX (A)		Chassis No:	VR2E26136573
Reg. Date:	24/11/2021 (Man. Year: 2021)		Odometer:	32958 km
Colour:	Blue			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,284.63	2,851.58	22,433.05	88.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,130.00	900.00	7,230.00	88.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,414.63	3,751.58	29,663.05	88.77
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	33,414.63	3,000.00	30,414.63	91.02
+ GST 8.00/8.00% (S\$)	2,673.17	240.00	2,433.17	91.02
Nett Amount (S\$)	36,087.80	3,240.00	32,847.80	91.02

INSPECTION

Date of Assignment:	14/02/2023	
Date Inspected:	15/02/2023	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Jul 2023)	
Parts:	N/A	NISSAN NV350 CARAVAN 2.0 DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL6380B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT PANEL	Not Necessary	1,426.70 FL	*- FL
2	1	*FRONT BUMPER	Not Necessary	634.50 FL	*- FL
3	1	*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	187.00 FL	*- FL
4	1	*FRONT BUMPER SIDE RETAINER RH	Not Necessary	186.00 FL	*- FL
5	1	*FRONT BUMPER SIDE RETAINER LH	Not Necessary	186.00 FL	*- FL
6	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	762.00 FL	*- FL
7	1	*FRONT GRILLE ASSEMBLY	Not Necessary	676.20 FL	*- FL
8	1	*FRONT GRILLE EMBLEM	Not Necessary	79.90 FL	*- FL
9	1	*FRONT HEADLAMP ASSEMBLY RH	Not Necessary	685.90 FL	*- FL
10	1	*FRONT HEADLAMP ASSEMBLY LH	Not Necessary	685.90 FL	*- FL
11	1	*FRONT CORNER PANEL RH	Not Necessary	597.70 FL	*- FL
12	1	*FRONT DOOR SIDE MIRROR ASSEMBLY RH	Not Necessary	616.80 FL	*- FL
13	1	*FRONT DOOR SIDE MIRROR COVER RH	Not Necessary	148.00 FL	*- FL
14	1	*FRONT DOOR RH	Not Necessary	2,540.30 FL	*- FL
15	1	*FRONT DOOR UPPER HINGE RH	Not Necessary	58.00 FL	*- FL
16	1	*FRONT DOOR LOWER HINGE RH	Not Necessary	58.00 FL	*- FL
17	1	*FRONT DOOR CHECKER RH	Not Necessary	74.50 FL	*- FL
18	1	*FRONT DOOR RUBBER SEAL RH	Not Necessary	73.20 FL	*- FL
19	1	*FRONT DOOR LOCK RH	Not Necessary	289.30 FL	*- FL
20	1	*FRONT DOOR LOCK CATCH RH	Not Necessary	58.10 FL	*- FL
21	1	*FRONT DOOR LOWER RUBBER SEAL RH	Not Necessary	93.70 FL	*- FL
22	1	*FRONT DOOR GLASS REGULATOR RH	Not Necessary	317.20 FL	*- FL
23	1	*FRONT DOOR GLASS REGULATOR MOTOR RH	Not Necessary	537.30 FL	*- FL
24	1	*FRONT DOOR BACK PANEL RH	Not Necessary	736.10 FL	*- FL
25	1	*FRONT STEP GARNISH RH	Not Necessary	277.40 FL	*- FL
26	1	*FRONT WHEEL RIM RH	Not Necessary	317.10 FL	*- FL
27	1	*FRONT WHEEL RIM CAP RH	Not Necessary	160.00 FL	*- FL
28	1	*FRONT WHEEL BEARING RH	Not Necessary	452.00 FL	*- FL
29	1	*FRONT SHOCK ABSORBER RH	Not Necessary	184.50 FL	*- FL
30	1	*FRONT LOWER ARM RH	Not Necessary	284.50 FL	*- FL
31	1	*FRONT KNUCKLE ARM RH	Not Necessary	459.20 FL	*- FL
32	1	*FRONT UPPER ARM RH	Not Necessary	350.00 FL	*- FL
33	1	*FRONT LOWER ARM BALL JOINT RH	Not Necessary	98.00 FL	*- FL
34	1	*SLIDING DOOR RH	Not Necessary	2,032.70 FL	*- FL
35	1	*SLIDING DOOR INNER TRIM BOARD RH	Not Necessary	458.40 FL	*- FL
36	1	*SLIDING DOOR WEATHERSTRIP RH	Not Necessary	156.30 FL	*- FL
37	1	*SLIDING DOOR OUTER HANDLE RH	Not Necessary	194.00 FL	*- FL
38	1	*SLIDING DOOR LOWER HINGE RH	Not Necessary	211.40 FL	*- FL
39	1	*SLIDING DOOR LOWER HINGE ROILER RH	Not Necessary	167.20 FL	*- FL
40	1	*SLIDING DOOR CENTRE RAILING RH	Not Necessary	505.90 FL	*- FL
41	1	*SLIDING DOOR CENTRE RAILING GARNISH RH	Not Necessary	384.50 FL	*- FL
42	1	*SLIDING DOOR CENTRE RAILING GARNISH SIDE COVER RH	Not Necessary	132.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SLIDING DOOR LOCK RH	Not Necessary	328.30 FL	*- FL
44	1		*SLIDING DOOR LOCK CATCH RH	Not Necessary	23.90 FL	*- FL
45	1		*REAR SIDE PANEL RH	Dented	2,164.20 FL	*2,164.20 FL
46	1		*REAR WHEEL RIM RH	Not Necessary	317.10 FL	*- FL
47	1		*REAR WHEEL RIM CAP RH	Scratched	160.00 FL	*160.00 FL
48	1		*REAR SHOCK ABSORBER RH	Not Necessary	128.90 FL	*- FL
49	1		*REAR WHEEL BEARING RH	Not Necessary	321.00 FL	*- FL
50	1		*REAR AXLE SHAFT RH	Not Necessary	458.00 FL	*- FL
51	1		*REAR AXLE HOUSING	Not Necessary	1,683.60 FL	*- FL
52	1		*REAR AXLE HOUSING SHAFT OIL SEAL	Not Necessary	64.00 FL	*- FL
53	1		*REAR BUMPER	Scratched / Broken	722.00 FL	*722.00 FL
54	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	73.50 FL	*- FL
55	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	73.50 FL	*- FL
56	1		*REAR TAILLAMP ASSEMBLY RH	Not Necessary	409.30 FL	*- FL
57	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
58	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*SET FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*SET FRONT DOOR INNER TRIM BOARD RH CLIPS	Not Necessary	50.00 FS	*- FS
61	1		*SET SLIDING DOOR INNER TRIM BOARD RH CLIPS	Not Necessary	50.00 FS	*- FS
62	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
63	1		*SLIDING DOOR GLASS SEALANT RH	Not Necessary	150.00 FS	*- FS
64	1		*REAR SIDE PANEL GLASS SEALANT RH	Not Necessary	150.00 FS	*- FS
65	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Not Necessary	150.00 FS	*- FS
66	1		*FRONT PANEL SEALANT	Not Necessary	150.00 FS	*- FS
67	1		*FRONT DOOR RH SEALANT	Not Necessary	150.00 FS	*- FS
68	1		*FRONT DOOR BACK PANEL RH SEALANT	Not Necessary	150.00 FS	*- FS
69	1		*SLIDING DOOR RH SEALANT	Not Necessary	150.00 FS	*- FS
70	1		*REAR SIDE PANEL RH SEALANT	Necessary	250.00 FS	*60.00 FS
71	1		*FRONT DOOR COMPANY STICKER RH	Not Necessary	150.00 FS	*- FS
72	1		*FRONT TYRE RH	Not Necessary	250.00 FS	*- FS
73	1		*REAR TYRE RH	Not Necessary	250.00 FS	*- FS
74	1		*REAR AXLE GEAR OIL (3L)	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	27,830.70	3,156.20
- List Item Discount on L Items 10.00/10.00% (\$)	2,546.07	304.62
Total Parts (\$)	25,284.63	2,851.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE & REFIX PARTS	New	2,600.00	400.00
2	TO SPRAY PAINT AFFECTED AREAS	New	2,200.00	400.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO REMOVE & REFIX REAR SIDE PANEL RH GLASS	New	150.00	0.00
5	TO REMOVE & REFIX SLIDING DOOR RH GLASS	New	150.00	0.00
6	TO TRANSFER SLIDING DOOR RH MECHANISM	New	150.00	0.00
7	TO TRANSFER FRONT DOOR RH MECHANISM	New	150.00	0.00
8	TO REMOVE & REFIX INTERIOR UPHOLSTRY TO FACILITATE REPAIRS	New	150.00	0.00
9	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	350.00	0.00
10	TO REMOVE & REFIX REAR UNDERCARRIAGE	New	500.00	0.00
11	TO CONDUCT FOUR WHEEL ALIGNMENT	New	150.00	0.00
12	TO REMOVE & REFIX FRONT AND REAR TYRE AND CONDUCT WHEEL BALANCING	New	150.00	0.00
13	TO REMOVE & REFIX AND ADJUST REAR AXLE GEARS TO FACILITATE REPAIRS	New	450.00	0.00
14	TO REMOVE & REFIX REAR BUMPER REVERSE SENSORS	New	150.00	30.00
15	TO APPLY ANTI RUST ON AFFECTED PARTS	New	150.00	40.00
16	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
17	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT. PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (\$\$)			8,130.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >