



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB22011635/Rqy3e2-1	
			Date: 15/03/2023	
			Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLT 647L	Veh. Inspected	SCH 7575J	
Policy No.	D21MFL0000447_01	Coverage (\$)	0.00	
Claim No.	MFL2022D0009196	Excess (\$)	0.00	
Assign From	CARINE KEK	Assign Date	13/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA NOAH	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	ZWR800355418	Colour	BLACK	
Odometer	279894 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DURUN	6 mm	
L/H Front Tyre	195/65 R15	DURUN	6 mm	
R/H Rear Tyre	195/65 R15	DURUN	6 mm	
L/H Rear Tyre	195/65 R15	DURUN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2022	Inspection Date	22/11/2022	
Survey held at	LAY AUTO GARAGE PTE LTD 38 TOH GUAN ROAD EAST #01-56 ENTERPRISE HUB SINGAPORE 608581			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	