

Your Ref: WAN.VK.5146741.Q

Date: 14<sup>th</sup> Jul 2023

Our Ref: CS1/LAW23001638/Dvy3e2

**M/s Riaz LLC**133 New Bridge Road  
#09-09 Chinatown Point  
Singapore 059413

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBB 5709Y  
INSURED VEHICLE: SJT 966P  
ACCIDENT DATE: 01/10/2019**

We thank you for your instruction on 10/02/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBB 5709Y from M/s Lee Appraisal Services.
- b) Survey report by FormTeam Consultancy with colour photographs.
- c) Final Repair Bill of FBB 5709Y from M/s Prospin Motorsports.
- d) Singapore Accident Statement of Vehicles SJT 966P.
- e) Police Report of Vehicles FBB 5709Y and SJT 966P
- f) Colour damaged vehicle photographs of FBB 5709Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

## 1. Information Recorded: -

Registration Number	: FBB 5709Y
Make & Model	: Yamaha T135
Chassis Number	: 5YP205173
Year of Registration	: 2007

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.