

# AUTOMOBILE HUB

## VEHICLE DETAILS

VEHICLE NO : SNH5701U 2022 NOV  
 VEHICLE MODEL : HYUNDAI AVANTE CN7  
 CHASSIS NO : KMHLN41ETNU340928

TP HSBC.

Hui Rong

## CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>Neu</i>	2	\$ 58.10	\$ 116.20
2	REAR BUMPER <i>Dented</i>	1	\$ 520.80	\$ 520.80
3	REAR BUMPER SIDE HOLDER <i>Neu</i>	2	\$ 48.90	\$ 97.80
4	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 394.80	\$ 394.80
5	REAR BUMPER REINFORCEMENT BRACKET <i>Dented</i>	4	\$ 24.90	\$ 99.60
6	REAR BUMPER CENTRE LAMP <i>Cracked</i>	1	\$ 281.40	\$ 281.40
7	REAR BUMPER REFLECTOR <i>Cracked.</i>	2	\$ 48.80	\$ 97.60
8	REAR BUMPER LOWER GARNISH <i>Dented</i>	1	\$ 380.60	\$ 380.60
9	REAR BUMPER SIDE UNDERCOVER <i>LH Dented</i>	2	\$ 98.60	\$ 197.20
10	REVERSE SENSOR <i>2 pieces damaged.</i>	4	\$ 249.20	\$ 996.80
11	REVERSE SENSOR HOLDER <i>Neu</i>	4	\$ 25.00	\$ 100.00
12	REVERSE SENSOR WIRE HARNESS <i>Neu</i>	4	\$ 445.50	\$ 1,782.00
13	REAR END PANEL <i>Dented.</i>	1	\$ 487.60	\$ 487.60
14	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 185.90	\$ 185.90
15	REAR END PANEL ANTENNA SENSOR OUTER <i>3rd</i>	1	\$ 265.70	\$ 265.70
16	REAR END PANEL ANTENNA SENSOR INNER <i>3rd</i>	1	\$ 285.60	\$ 285.60
17	TAILLAMP <i>3rd</i>	2	\$ 871.20	\$ 1,742.40
18	TAILLAMP PANEL <i>3rd</i>	2	\$ 254.60	\$ 509.20
19	BOOTLID <i>Repair</i>	1	\$ 2,023.40	\$ 2,023.40
20	BOOTLID LOCK <i>new</i>	1	\$ 185.70	\$ 185.70
21	BOOTLID WEATHERSTRIFE <i>new</i>	1	\$ 148.20	\$ 148.20
22	BOOTLID OUTER GARNISH (OUTER) <i>3rd</i>	1	\$ 745.60	\$ 745.60
23	BOOTLID OUTER GARNISH (INNER) <i>3rd</i>	1	\$ 485.60	\$ 485.60
24	BOOTLID CENTRE LAMP	1	\$ 1,185.80	\$ 1,185.80
25	HYUNDAI LOGO <i>3rd</i>	1	\$ 54.50	\$ 54.50
26	AVANTE WORDING	1	\$ 51.10	\$ 51.10
27	ELITE EMBLEM <i>new</i>	1	\$ 45.90	\$ 45.90
28	REAR BLIND SPOT SENSOR <i>3rd</i>	2	\$ 1,296.40	\$ 2,592.80
29	REAR BLIND SPOT SENSOR BRACKET <i>3rd</i>	2	\$ 169.30	\$ 338.60
30	SPARE TYRE PANEL <i>Repair</i>	1	\$ 764.50	\$ 764.50
31	SPARE TYRE PANEL TOP COVER <i>new neu</i>	1	\$ 361.40	\$ 361.40
32	REAR FENDER INNER TRIM <i>Neu</i>	2	\$ 328.40	\$ 656.80

3296.80  
 2637.44

TOTAL PRICE: \$ 16,844.60  
 LESS 20% \$ 3,368.92  
 SUB TOTAL PRICE: \$ 13,475.68

## SPECIAL NETT ITEMS

ITEMS	QTY	UNIT PRICE	TOTAL

1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 30.00	\$ 30.00	✓
2	REAR NUMBER PLATE HOLDER <i>Delid</i>	1	\$ 30.00	\$ 30.00	✓
3	REAR BUMPER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00	✓
4	REAR BUMPER SIDE UNDERCOVER CLIPS <i>New</i>	2 SET	\$ 20.00	\$ 40.00	20
5	REAR END PANEL TOP GARNISH CLIPS <i>New</i>	1 SET	\$ 20.00	\$ 20.00	✓
6	REAR END PANEL SEALANT <i>New</i>	1	\$ 60.00	\$ 60.00	✓
7	REAR FENDER INNER TRIM CLIPS <i>New New</i>	2 SET	\$ 30.00	\$ 60.00	X
			TOTAL :	\$ 270.00	

190

**LABOUR**

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	800	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	60	
5	TO REMOVE UPHOLSTERY & REAR SEAT	\$ 380.00	60	
6	TO TRANSFER BOOTLID FITTINGS	\$ 150.00	X	
7	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
8	TO REMOVE REAR CAMERA	\$ 100.00	X	
9	TO CALIBRATE REAR BIND SPOT SENSORS	\$ 380.00	X	
TOTAL		\$ 4,310.00	1600	

**ESTIMATE REPORT**

TOTAL PARTS COST: \$ 13,745.68  
 TOTAL LABOUR COST: \$ 4,310.00  
 TOTAL REPAIR COST: \$ 18,055.68

total: 4427.44  
 1/5: 3.5K  
 05 Days

**APPROVED DETAILS**

SURVEYOR:

FAX:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: