

ASS. REC. BY: AMC

REF:

CS/CT123001641/Rvp3

237H

06-2025/AN

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJM 7089Lat Workshop m/s XINYA AUTOof 1002, BUKIT MEKAR LK3 #01-75Insured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 74K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJM 7089L Yr Regn: 2009 JANType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA ESTIMA KEEN 2.4A c.c. 2362Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 234506 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACR500076903Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 03/02/23 D.O.I. 15/02/23Survey held at XINYA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LHM R-SSK

Date/Time, File Pass to?

☐ : Prell. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Photos

Others

Report Format: _____

Lump Sum / I.B.R. (\$) _____

XINYA AUTO SERVICES PTE LTD

Add: BLK 1002, BUKIT MERAH LANE 3 #01 -75, Singapore 159719

E-mail : xinyaauto@gmail.com

Tel: 6270 3481 Fax: 6278 7522

Date : 31-May-21

Address : MR NG CHOON CHWEE
BLK 192 BISHAN ST.13
#07-501
SINGAPORE 570192

Reference : TP 1335/02/23
Vehicle No : SJM 7089L
Make/Model : TOYOTA ESTIMA
Insurance Co : NTUC

- To resurvey before/after
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

RE : QUOTATION REPAIRS TO SJM 7089L FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

		QTY	AMT \$
1)	REAR BUMPER <i>cm</i>	1	\$ 899.50*
2)	REAR BUMPER RETAINER <i>X</i>	1	\$ 86.95
3)	TOW HOOK COVER <i>X</i>	1	\$ 36.90
4)	REAR BUMPER REFLECTOR <i>?</i>	1	\$ 69.55
5)	REAR END PANEL <i>X</i>	1	\$ 755.90
6)	REAR BUMPER BRACKET <i>X</i>	1	\$ 86.50
7)	REAR TAIL GATE <i>si</i>	1	\$ 1,753.80
8)	REAR TAIL GATE LOCK <i>X</i>	1	\$ 490.30
9)	REAR TAIL GATE WEATHERSTRIPE <i>ur</i>	1	\$ 372.20

LIST PRICE TOTAL \$ 4,551.60
LESS DISCOUNT 25% \$ 1,137.90
LIST PRICE TOTAL AFTER LESS \$ 3,413.70

10)	WINDSCREEN SEALANT <i>m</i>	\$ 50.80 <i>30</i>
11)	WINDSCREEN CLIPS <i>m</i>	\$ 12.00

NETT PRICE TOTAL \$ 62.00

TOTAL PARTS COST \$ 3,475.70

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE REAR BUMPER, TAILGATE AND TO PANEL BEAT CUT & WELD END PANEL	\$ 1,000.00 <i>2500 500</i> (5 DAYS)
2)	TO PUTTY & SPRAY PAINT REAR BUMPER, TAILGATE AND OTHER AFFECTED AREA	\$ 880.00 <i>1500 600</i> (4 PANEL)
3)	TO CHECK & RECTIFY WIRING	\$ 60.00 <i>X</i>
4)	TO REMOVE & REPLACE REAR WINDSCREEN GLASS, CHECK FOR WATER TIGHT.	\$ 180.00 <i>120</i>
5)	TUFF KOTE	\$ 180.00 <i>40</i>

Panel
Hy 90010068

4 days

1/5

15/02/23 @ 1440

Resun after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

LABOUR TOTAL

TOTAL ESTIMATED REPAIR COST

\$ 2,300.00

\$ 5,775.70

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	237H

Vehicle Details

Vehicle No.:	SJM7089L
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2023
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	2AZF194729
Chassis No.:	ACR500076903
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$29,539.00
Original Registration Date:	14 Jan 2009
First Registration Date:	14 Jan 2009
Transfer Count:	3
Actual ARF Paid:	\$29,539.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	13 Jan 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$18,489.00
Total Rebate Amount:	\$18,489.00

Toyota Estima 2.4A Aeras (COE till 01/2028)

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

GV CARS FINANCING

Price **\$62,800**

Depreciation ⓘ **\$12,750 /yr**

Reg Date

23-Jan-2008

(4yrs 11mths 3days COE left)

Mileage **N.A.**

Manufactured ⓘ

2007

Road Tax ⓘ **\$2,457 /yr**

Transmission

Auto

Dereg Value ⓘ **\$25,749 as of today (change)**

OMV ⓘ

\$26,855

COE ⓘ **\$52,271**

ARF ⓘ

\$29,541

Engine Cap **2,362 cc**

Power

125.0 kW (167 bhp)

Curb Weight ⓘ **1,710 kg**

No. of Owners ⓘ

3