

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08

Sin Ming AutoCare Singapore 575721

Tel No. : 64556268 Fax No. : 64555166

E-Mail : info@ktauto.com.sg

Website : www.ktauto.com.sg

Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

Estimate sent to LK

28/6/2023

MSIG INSURANCE (SINGAPORE) PTE LTD

4 SHENTON WAY,

#21-01 SGX CENTRE 2, SINGAPORE 068807

Attention : Motor Claim Department

Contact : 68277660 / 65942555 Fax No. : 62256371 / 62257402

Estimate : ES000508

Date : 14/02/2023

Vehicle Num. : SLU 2396 S

Make/Model : AUDI Q2-2017

Chassis/Eng# : WAUZZZGA2JA035342/CHZ584028

Accident Date : 14/02/2023

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT FENDER - LH		985.00
2.	1	FRONT BUMPER		1,950.00
3.	1 LH	FRONT BUMPER BRACKET		115.00
4.	1	FRONT WHEEL ARCH PROTECTOR		495.00
5.	1 LH	FRONT HEAD LAMP		2,150.00
6.	LH	FRONT SPORT RIM		680.00
List TotalS\$:				6,375.00
NETT ITEMS :				
1.		COMPUTERIZED FOUR WHEEL ALIGNMENT		120.00
Nett Total S\$:				120.00
LABOUR :				
LABOUR FEES:				
TO KNOCK AND REPAIR DAMAGED PARTS				1,120.00
TO REMOVE AND CHANGE ALL DAMAGED PARTS				
TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS				960.00
TO SPRAY PAINT ALL DAMAGED PARTS				
TO PROGRAM AND RE-CALIBRATE HEADLAMP UNIT				280.00
Labour Total S\$:				2,360.00

E. & O.E.

Total S\$: 8,855.00

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
We thank you for your kind attention. Your prompt reply is greatly appreciated.