

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23001643/UQY3M4**Date:** 17/03/2023**REFERENCE**

Insured/Claimant:	NICOLE TAN KIM ENG	Policy No:	SP2004367750-01
Date of Loss:	10/02/2023	Nature of Claim:	OD
		Claim No:	202332005316

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH5016P		
Make & Model:	MAZDA 3, 1.5 5-DOOR HATCHBACK L SP.6EAT (A)	Engine No:	P520328386
Reg. Date:	18/12/2015 (Man. Year: 2015)	Chassis No:	JM6BM44A8G0323417
Colour:	White	Odometer:	83044 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$40,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,955.80	1,608.20	347.60	17.77
Miscellaneous Items	40.00	35.00	5.00	12.50
Labour	830.00	570.00	260.00	31.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,825.80	2,213.20	612.60	21.68
+ GST 8.00/8.00% (S\$)	226.06	177.06	49.00	21.68
Nett Amount (S\$)	3,051.86	2,390.26	661.60	21.68

INSPECTION

Date of Assignment:	14/02/2023	Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	16/02/2023	Inspected At:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2023)
Parts:	144	MAZDA 3 1.5 5-DOOR HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH5016P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT GRILLE (WCP)	Cracked	380.00 F	*380.00 F
2	1		*FRT GRILLE CENTER LOGO (WCP)	Scratched	35.00 F	*35.00 F
3	2		*FRT GRILLE CHROME (WCP)	Cracked/Scratched	250.00 F	*250.00 F
4	2		*GRILLE REAR BRACKET (WCP)	Not Necessary	56.00 F	*- F
5	6		*GRILLE CLIP (WCP)	Necessary	15.00 F	*15.00 F
6	1		*GRILLE TOP GARNISH (WCP)	Dented/Deformed	195.00 F	*195.00 F
7	6		*GRILLE TOP GARNISH RIVERTS (WCP)	Necessary	33.00 F	*33.00 F
8	1		*FRT BUMPER (WCP)	Deformed/Torn	490.00 F	*490.00 F
9	10		*FRT BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
10	1		*FRT BUMPER REINFORCEMENT (WCP)	Repair	260.00 F	*- F
11	2		*FRT BUMPER SCREW COVER (WCP)	Missing	44.00 F	*44.00 F

F=Franchise part.

Sub Total (\$\$)	1,778.00	1,462.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	177.80	146.20
Total Parts (\$\$)	1,955.80	1,608.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	NUMBER PLATE (BENT)	40.00	35.00
Sub Total (\$\$)			40.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRE CHECKING	New	30.00	20.00
2	LABOUR CHARGE	New	400.00	250.00
3	SPRAY PAINTING (PEARL)	New	400.00	300.00
Gross Labour Cost (\$\$)			830.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >