

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 17 Feb 2023

**Preliminary Advice**

Vehicle No	: SNH5016P	Accident Date	: 10/02/2023
Make	: MAZDA 3	Policy No.	: SP2004367750-01
Assignment Date	: 14/02/2023	Excess	: S\$0.00
Date of Inspection	: 16/02/2023	Est. Duration of Repair	: 3
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,825.80
Revised Amount	:S\$	2,176.90
Check Items (Estimated)	:S\$	61.60
Total	:S\$	2,238.50

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	23,900.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,100.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO 2ND HAND PARTS AVAILABLE.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.