

ASS. REC. BY:

REF:

Alfa 230016491kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of Yishun

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

2pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<i>(Signature)</i>	
N/S	O/S
<i>(Signature)</i>	

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SN 853P Yr Regn: 04, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes 3 c.c 1496

Colour: M. Grey A/C: Insured / Std / Nil / NA

Sp. Reading: 112605 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JM8BN22A8H0151056

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: TOYO

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TOYO

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 13/2/12

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 6/3/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

& 1st

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/1/4 21:20 @ 3900d. Carhu

Date/Time, File Pass to?

: Prell. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Transportation

S - RS. \$

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLN 853P
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 13/02/2023
 TP Veh Reg No: SMV6645E

Not Notified
1/1 Pny &
Recovery After Repair

Estimate No: ES2300173/YISHUN

Date: 20 Feb 2023

Policy No: 5111995660-03

Veh Reg No: SLN853P

Make/Model: MAZDA MAZDA3
 SEDAN 1.5 AT EU6

Chassis No: JM6BN22A8H0151056

Engine No: P520442312

Reg. Date: 21/04/2017

Estimate Repair Cost to Vehicle No :SLN853P

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	1,128.60	1 PC	1,128.60	✓
2 REAR BUMPER REINFORCEMENT	564.20	1 PC	564.20	✓
3 REAR BUMPER TOW COVER	17.20	1 PC	17.20	✓
4 REAR BOOT	1,005.30	1 PC	1,005.30	✓
5 REAR BOOT LOGO	178.20	1 PC	178.20	✓
6 REAR BOOT EMBLEM (3)	156.10	1 PC	156.10	✓
7 REAR BOOT EMBLEM (SKYACTIV)	66.80	1 PC	66.80	✓
8 REAR BUMPER CLIPS	5.50	6 PCS	33.00	✓
9 FRONT BUMPER	985.30	1 PC	985.30	✓
10 FRONT BUMPER CLIPS	5.50	6 PCS	33.00	✓
11 FRONT GRILLE BASE	355.50	1 PC	355.50	✓
12 FRONT GRILLE LOGO	51.50	1 PC	51.50	✓
13 FRT GRILLE LOWER MOULDINGS	191.70	2 PCS	383.40	✓
			4,958.10	
		Less 20%	991.62	3,966.48
Special Net				
14 REVERSE SENSOR	200.00	1 SET	200.00	✓
15 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
			235.00	235.00
Labour				
16 REMOVE & REFIX REAR BUMPER ASSY, REINFORCEMENT, REAR BOOT, TO KNOCK & REPAIR REAR PANEL AND REALIGN THE SAME	600.00	1 LA	600.00	400
17 PUTTY & RESPRAY ON REAR PANEL, BOOT, REAR BUMPER, BUMPER REINFORCEMENT	800.00	1 LA	800.00	600
18 REMOVE & REFIX FRT BUMPER, GRILLE, CHECK HEADLAMPS, KNOCK & REPAIR FRT BUMPER REINFORCEMENT	400.00	1 LA	400.00	280
19 PUTTY & RESPRAY ON FRT BUMPER, REINFORCEMENT	400.00	1 LA	400.00	320
20 RUSTPROOFING	30.00	1 LA	30.00	✓
			2,230.00	2,230.00

Total S\$ 6,431.48

Add GST @ 8% 514.52

Total Amount Payable S\$ 6,946.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE