



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD C/O KELVIN CHIA PARTNERSHIP 6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC TOWER FOUR SINGAPORE 038986			Ref: CS3/CTI21011210/Tnp3e2-1 Date: 21/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 8793S	Veh. Inspected	FBK 401U	
Policy No.	DMPCSNW00123152103	Coverage (\$)	0.00	
Claim No.	SS/AR/2022003293.CI(mpd)	Excess (\$)	0.00	
Assign From	HAZDI (KC PARTNERSHIP)	Assign Date	10/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400X	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JH2NC4791EK000164	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	PIRELLI	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	PIRELLI	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/09/2021	Inspection Date	03/11/2021	
Survey held at	HL CYCLE PL 1 KAKI BUKIT AVE 6 #02-58 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	