



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC23001652/Kpa3q2 Date: 27/06/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 7999L	Veh. Inspected	GBJ 7335L
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/23/23/VC00/026851	Excess (\$)	0.00
	Assign From		Assign Date	14/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ SPRINTER (A)	c.c	2143
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WDB9076332P092391	Colour	WHITE
	Odometer	149653 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/65 R16	MICHELIN	8 mm
	L/H Front Tyre	235/65 R16	MICHELIN	8 mm
	R/H Rear Tyre	235/65 R16	MICHELIN	8 mm
	L/H Rear Tyre	235/65 R16	MICHELIN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/01/2023	Inspection Date	15/02/2023
	Survey held at	160 Sin Ming Drive #02-01 AutoCity S 575722		
	Repairer	MEGA AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 7335L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILLAMP RH	CRACKED	1,200.00	920.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,850.00	-
	LESS 10% DISCOUNT		-305.00	-92.00
			2,745.00	828.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR FENDER STICKER RH (SN)	NECESSARY	450.00	300.00
			450.00	300.00
	<u>LABOUR</u>			
	STRAIGHTEN & PANEL BEAT ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF REAR FENDER RH		850.00	400.00
	RESPRAY ACCIDENT AREA.		750.00	300.00
			1,600.00	700.00
	GRAND TOTAL		4,795.00	1,828.00
	RECOMMENDED COST OF REPAIRS			1,828.00

Report Ref No. CC4/LPC23001652/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 7335L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 7335L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

