

Customer Details:

Fedex
Federal Express (s) Pte Ltd
90 Alps Ave
Singapore 498746
Fax: 69222550

View Photo

Accident Photo

Vehicle Details

Vehicle No : GBJ 7335 L
Vehicle Make : Mercedes
Vehicle Model : Sprinter 0
Vehicle Engine No : WDB9076332P092391
Engine Chasis No :
Mileage :

Owner's Accident Details

Job No : SN-002012-23-20002
JobCategory : TP - Lump Sum
Date of Accident :
Owner's Insurer : ,
Location of Accident : ,

Suveyor's Details

Surveyor Name :
Surveyor Company :
Surveyor ContactNo :
Surveyor FaxNo :
Quotation Submission Date :
Surveyor Approve Date :
Supplementary Date :
Supplementary Approve Date :

Item No	Ref No	Description	QTY	Unit List Price	Mark Up / Discount %	Mark Up / Discount Price	Total Price	Rev Qty	Rev Unit Price	Remarks	Final Total Price	Surveyor Approval
<u>Materials</u>												
1	1	Taillamp RH	1	\$1,200.00	-10.00	\$1,080.00	\$1,080.00	0	0		\$0.00	_____
2	2	Rear Fender RH	1	\$1,850.00	-10.00	\$1,665.00	\$1,665.00	0	0		\$0.00	_____
							Material Total: \$2,745.00	Final Sub-Total : \$0.00				
<u>Special Nett Items</u>												
1	3	Rear Fender Sticker RH	1	\$450.00	0.00	\$450.00	\$450.00	0	0		\$0.00	_____
							Special Nett Items Total: \$450.00	Final Sub-Total : \$0.00				
<u>Labour</u>												
1	4	Straighten & Panel Beat Accident Area	1	\$850.00	0.00	\$850.00	\$850.00	0	0		\$0.00	_____
2	5	Respray Accident Area	1	\$750.00	0.00	\$750.00	\$750.00	0	0		\$0.00	_____
							Labour Total: \$1,600.00	Final Sub-Total : \$0.00				
<u>Others</u>												
							Others Total: \$0.00	Final Sub-Total : \$0.00				
							Total Price: \$4,795.00	Final Total Price : \$0.00				