

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

not allowed
while
meant
20/3/23
weight of the
5 days
4/5 & 6/100

M/S : KEE HWA HON (JI HUA FENG)
APT BLK 9 BEDOK SOUTH AVENUE 2 #02-528
460009

Estimate No: EST1509327
Date: 13 Feb 2023
Policy No: 7220142088
Veh Reg No: SLW2999S
Make/Model: TOYOTA WISH 1.8 CVT
Chassis No: JTDGG20W70J008889
Engine No: 2ZR0A58876
Reg. Date: 06/02/2018

ATTN: LONPAC
Your Ref No: TP 0223-7265
Claim Type: Third Party
Accident Date: 10/02/2023
TP Veh Reg No: GBD4678Z

Estimate Repair Cost to Vehicle No :SLW2999S

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT <i>3045.00</i>	1,775.900	1 PC	1,775.90	—
2 REAR BOOT RUBBER <i>7m</i>	403.7000	1 PC	403.70	—
3 REAR BOOT TOP LOCK <i>2m</i>	495.5000	1 PC	495.50	—
4 REAR BOOT BOTTOM LOCK <i>17</i>	60.8000	1 PC	60.80	X
5 REAR BOOT GLASS MOULDING <i>1m</i>	240.7000	1 SET	240.70	—
6 REAR BOOT TOYOTA LOGO <i>1m</i>	72.2000	1 PC	72.20	—
7 REARBOOT VALVE MATIC WORDING <i>1m</i>	80.5000	1 PC	80.50	—
8 REAR BOOTLAMP - LH/RH <i>one</i>	392.4000	2 PC	784.80	—
9 REAR BOOT OUTER CHROME <i>one</i>	348.6000	1 PC	348.60	—
10 REAR BOOT LOCK SENSOR <i>one</i>	148.6000	1 PC	148.60	—
11 REAR BOOT NUMBER PLATE LAMP - RH/LH <i>17</i>	105.4000	2 PCS	210.80	X
12 REAR BOOT INNER TRIM <i>SUC</i>	380.5000	1 PC	380.50	X
13 REAR BUMPER <i>DD</i>	720.2000	1 PC	720.20	—
14 REAR BUMPER SIDE HOLDER - RH/LH <i>1m</i>	105.6000	2 PC	211.20	—
15 REAR BUMPER CLIPS <i>1m</i>	5.5000	10 PC	55.00	—
16 REAR BUMPER BRACKETS - RH/LH <i>1/5 1/1 0/5 DD</i>	110.7000	2 PC	221.40	1 PC
17 REAR BUMPER REFLECTORS - RH/LH <i>17</i>	79.7000	2 PC	159.40	X
18 TAILLAMP ASSY - RH/LH <i>1/3 1/1 0/5 DD</i>	425.9000	2 PCS	851.80	1 PC
19 REAR END PANEL <i>DD/3m</i>	644.9000	1 PC	644.90	—
20 REAR END PANEL TOP GARNISH <i>7m</i>	358.3000	1 PC	358.30	—
			8,175.30	
	Less 25%		2,043.83	6,131.48
Special Net				
21 REAR BUMPER SENSOR <i>shock</i>	220.0000	1 SET	220.00	200
22 REAR NUMBER PLATE WITH CASING <i>3m</i>	45.0000	1 SET	45.00	40
23 SEALANT <i>Rear window</i>	20.0000	2 PC	40.00	—
24 SPONGE TAPE <i>Rear window</i>	20.0000	1 PC	20.00	—
			325.00	325.00
Labour				
25 TO KNOCK OUT DENTS ON REAR FENDER,CUT/WELD REAR PANEL,, REMOVE, REPLACE ACCIDENT PARTS	1,000.000	1 JOB	1,000.00	800
26 TO RESPRAY PAINT ON ACCIDENT PORTIONS (PEARL)	1,500.000	1 JOB	1,500.00	1000
27 TO TUFF-KOTE	90.0000	1 JOB	90.00	60
28 TO CHECK WIRING	50.0000	1 JOB	50.00	20
29 TO REMOVE, REFIX REAR GARNISH,CARPET & RELATED PARTS	150.0000	1 JOB	150.00	80
30 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00	50

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : KEE HWA HON (JI HUA FENG)
APT BLK 9 BEDOK SOUTH AVENUE 2 #02-528
460009

ATTN: LONPAC

Your Ref No: TP 0223-7265

Claim Type: Third Party

Accident Date: 10/02/2023

TP Veh Reg No: GBD4678Z

Estimate No: EST1509327

Date: 13 Feb 2023

Policy No: 7220142088

Veh Reg No: SLW2999S

Make/Model: TOYOTA WISH 1.8 CVT

Chassis No: JTDGG20W70J008889

Engine No: 2ZR0A58876

Reg. Date: 06/02/2018

Estimate Repair Cost to Vehicle No :SLW2999S

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
31 TO REMOVE, REFIT REAR BOOT GLASS	180.0000	1 JOB	180.00	120
32 TO TRANSFER REAR BOOT	80.0000	1 JOB	80.00	60
			3,150.00	3,150.00
Total			S\$ 9,606.48	
Add GST @ 8%			768.52	
Total Amount Payable			S\$ 10,375.00	

TOTAL: SINGAPORE DOLLAR TEN THOUSAND THREE HUNDRED SEVENTY FIVE ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6876-20
252
515752
300
2190
764752