

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : KEE HWA HON (JI HUA FENG)

APT BLK 9 BEDOK SOUTH AVENUE 2 #02-528
 460009

Estimate No: EST1509327

Date: 13 Feb 2023

Policy No: 7220142088

Veh Reg No: SLW2999S

Make/Model: TOYOTA WISH 1.8 CVT

Chassis No: JTDGG20W70J008889

Engine No: 2ZR0A58876

Reg. Date: 06/02/2018

ATTN: LONPAC

Your Ref No: TP 0223-7265

Claim Type: Third Party

Accident Date: 10/02/2023

TP Veh Reg No: GBD4678Z

Estimate Repair Cost to Vehicle No :SLW2999S

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 REAR BOOT	1,775.900	1 PC	1,775.90	
2 REAR BOOT RUBBER	403.7000	1 PC	403.70	
3 REAR BOOT TOP LOCK	495.5000	1 PCS	495.50	
4 REAR BOOT BOTTOM LOCK	60.8000	1 PCS	60.80	
5 REAR BOOT GLAASS MOULDING	240.7000	1 SET	240.70	
6 REAR BOOT TOYOTA LOGO	72.2000	1 PCS	72.20	
7 REARBOOT VALVE MATIC WORDING	80.5000	1 PCS	80.50	
8 REAR BOOTLAMP - LH/RH	392.4000	2 PCS	784.80	
9 REAR BOOT OUTER CHROME	348.6000	1 PCS	348.60	
10 REAR BOOT LOCK SENSOR	148.6000	1 PC	148.60	
11 REAR BOOT NUMBER PLATE LAMP - RH/LH	105.4000	2 PCS	210.80	
12 REAR BOOT INNER TRIM	380.5000	1 PCS	380.50	
13 REAR BUMPER	720.2000	1 PC	720.20	
14 REAR BUMPER SIDE HOLDER - RH/LH	105.6000	2 PCS	211.20	
15 REAR BUMPER CLIPS	5.5000	1 PC	5.50	
16 REAR BUMPER BRACKETS -MRH/LH	110.7000	2 PC	221.40	
17 REAR BUMPER REFLECTORS - RH/LH	79.7000	2 PC	159.40	
18 TAILLAMP ASSY - RH/LH	425.9000	2 PCS	851.80	
19 REAR END PANEL	644.9000	1 PC	644.90	
20 REAR END PANEL TOP GARNISH	358.3000	1 PC	358.30	
			8,175.30	
		Less 25%	2,043.83	6,131.48
Special Net				
21 REAR BUMPER SENSOR	220.0000	1 SET	220.00	
22 REAR NUMBER PLATE WITH CASING	45.0000	1 SET	45.00	
23 SEALANT	20.0000	2 PC	40.00	
24 SPONGE TAPE	20.0000	1 PCS	20.00	
			325.00	325.00
Labour				
25 TO KNOCK OUT DENTS ON REAR FENDER,CUT/WELD REAR PANEL,, REMOVE, REPLACE ACCIDENT PARTS	1,000.000	1 JOB	1,000.00	
26 TO RESPRAY PAINT ON ACCIDENT PORTIONS (PEARL)	1,500.000	1 JOB	1,500.00	
27 TO TUFF-KOTE	90.0000	1 JOB	90.00	
28 TO CHECK WIRING	50.0000	1 JOB	50.00	
29 TO REMOVE, REFIX REAR GARNISH,CARPET & RELATED PARTS	150.0000	1 JOB	150.00	
30 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : KEE HWA HON (JI HUA FENG)
APT BLK 9 BEDOK SOUTH AVENUE 2 #02-528
460009

Estimate No: EST1509327
Date: 13 Feb 2023
Policy No: 7220142088
Veh Reg No: SLW2999S
Make/Model: TOYOTA WISH 1.8 CVT
Chassis No: JTDGG20W70J008889
Engine No: 2ZR0A58876
Reg. Date: 06/02/2018

ATTN: LONPAC
Your Ref No: TP 0223-7265
Claim Type: Third Party
Accident Date: 10/02/2023
TP Veh Reg No: GBD4678Z

Estimate Repair Cost to Vehicle No :SLW2999S

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
31 TO REMOVE, REFIT REAR BOOT GLASS	180.0000	1 JOB	180.00	
32 TO TRANSFER REAR BOOT	80.0000	1 JOB	80.00	
			3,150.00	3,150.00
			Total	S\$ 9,606.48
			Add GST @ 8%	768.52
			Total Amount Payable	<u>S\$ 10,375.00</u>

TOTAL: SINGAPORE DOLLAR TEN THOUSAND THREE HUNDRED SEVENTY FIVE ONLY

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE