



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23001663/Kqy3e2
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1 HEMMANT ROAD SINGAPORE 438675		Date:	13/03/2023
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GZ 3296Z	Veh. Inspected	SLR 7041Z
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/005	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	15/02/2023
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHD841CMJU533402	Colour	METALLIC RED
Odometer	137130 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55Z R16	ALTENZO	6 mm
L/H Front Tyre	205/55Z R16	ALTENZO	6 mm
R/H Rear Tyre	205/55Z R16	ALTENZO	7 mm
L/H Rear Tyre	205/55Z R16	ALTENZO	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/02/2023	Inspection Date	16/02/2023
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	