



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
Our Ref : TP0073/12/22 Date : 16/12/2022

THIRD PARTY CLAIM

M/S : LIM HWEE MENG
BLK 498M TAMPINES STREET 45
#04-496
SINGAPORE 529498

Attn :

Claiming CTI.

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SMV5762G - HONDA FREED
INSURED : LIM HWEE MENG
DATE OF ACCIDENT : 14/12/2022
POLICY NO : MP39127

ENGINE# :
CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost \$	U/Price \$	Total \$	
Replacement of Parts					
1 rear windscreen rubber moulding <i>Hec</i>	10	38.00	38.00	38.00	✓
2 rear boot <i>Buc</i>	10	1035.00	1035.00	1,035.00	✓
3 rear boot lamp L&R <i>Cut</i>	20	293.00	293.00	586.00	✓
4 rear boot H emblem <i>Hec</i>	10	42.00	42.00	42.00	✓
5 rear boot FREED emblem <i>Hec</i>	10	57.00	57.00	57.00	✓
6 rear number plate lamp chrome moulding <i>HH</i>	10	188.00	188.00	188.00	X
7 rear boot lock top <i>not lost</i>	10	102.00	102.00	102.00	✓
8 rear boot lower lock catch <i>Key</i>	10	33.00	33.00	33.00	X
9 rear boot handle cover <i>HH</i>	10	20.00	20.00	20.00	X
10 rear boot damper L&R <i>HH</i>	20	218.00	218.00	436.00	X
11 rear lamp assy L&R <i>0/5 Cut H/S RM</i>	20	570.00	570.00	1,140.00	✓
12 rear bumper <i>damaged</i>	10	570.00	570.00	570.00	✓
14 rear bumper reflector lamp L&R <i>HH</i>	20	53.00	53.00	106.00	X
15 rear boot rubber <i>Sn</i>	10	113.00	113.00	113.00	X
16 rear bumper inner end panel <i>new</i>	10	480.00	480.00	480.00	X
17 rear end panel inner center garnish <i>Sn</i>	10	72.00	72.00	72.00	X
18 rear boot inner finisher <i>many crack</i>	10	248.00	248.00	248.00	✓
19 rear bumper parking sensor <i>Down 2pc original 2pc normal</i>	40	278.00	278.00	1,112.00	✓
20 rear bumper side retainer <i>Sn</i>	20	18.00	18.00	36.00	X
				6,414.00	

less 20%

\$5,131.20

Total Material

Special Nett Items

21 rear windscreen sealant <i>Hec</i>	10	45.00	45.00	45.00	401-
22 rear number plate w/casing <i>HH</i>	10	45.00	45.00	45.00	X
				90.00	



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg

Your Ref :
Our Ref : TP0073/12/22

Page : 2/2
Date : 16/12/2022

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Total s/Nett				\$90.00
Labour & Misc				
1 Remove & install rear windscreen.			150.00 120/-	
2 Remove & install r/boot, r/lamp, r/bumper, r/fender, r/end panel and knocking all the damaged parts and restraighthen body.			850.00 600/-	
3 Spray painting.			800.00 600/-	
4 Check wiring system.			25.00	
5 Renew parking snensor and reset.			100.00 40/-	
6 Remove & install r/boot carpet, seat and finisher.			100.00 80/-	
			2,025.00	
			0.00	
Total Labour			\$2,025.00	
Nett Total Before Gst			\$7,246.20	

Your faithfully

NPH AUTO SERVICE
(Manager)

16/12/2022 e 10am

Kia Audi

2/sun

(Signature)

LKK Auto

(Signature)

Check part prices
4 day.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: