

**Ding Auto Pte Ltd** (Co.Reg.No:201311788Z)

176 Sin Ming Drive #04-06, Sin Ming Autocare

Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

|                               |                                   |                       |                   |
|-------------------------------|-----------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (Own Damage)                   | Ref. No:              |                   |
| Policy No:                    | SP2002589079                      | Date of Loss:         | 14/02/2023        |
| Vehicle Reg. No.:             | <b>SLN3344Y</b>                   | Driveable?            |                   |
| Driver Age/Info:              | / MALE                            | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                | Third Party Involved? | YES               |
| Insured/Claimant:             | TRILLIUM LEASING PTE LTD          | Contact No:           | +6591182220       |
| Driver:                       | TAN YEN YANG                      |                       |                   |
| Make/Model:                   | TOYOTA COROLLA ALTIS, 1.6 CVT (A) | Vehicle Reg. Date:    | 19/04/2017        |
| Vehicle Colour:               | Red                               |                       |                   |
| Engine No:                    | 1ZRY343115                        | Chassis No:           | MR053REH104561394 |
| Odometer:                     | 237554 KM                         |                       |                   |
| Paint Type:                   |                                   |                       |                   |
| Total Loss?                   | <b>NO</b>                         |                       |                   |
| Est. Duration of Repair (day) | 15                                |                       |                   |
| Present Location:             | DING AUTO PTE LTD (HQ)            |                       |                   |

**COST OF CLAIMS**

|                           | <b>Amount</b>    |
|---------------------------|------------------|
| Parts                     | 8,492.00         |
| Miscellaneous Items       | 260.00           |
| Labour                    | 3,040.00         |
| Paintwork Labour          | 0.00             |
| Towing                    | 0.00             |
| <b>Gross Total (\$\$)</b> | <b>11,792.00</b> |
| <b>+ GST 8.00% (\$\$)</b> | <b>943.36</b>    |
| <b>Nett Amount (\$\$)</b> | <b>12,735.36</b> |

This claim is handled by: **HENRY LEE YOON SANG**Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 14 Feb 2023)

**Parts:** 143      TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** Ding Auto Pte Ltd/SLN3344Y/14/02/2023 17:57

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No. | Qty | Part No. | Particulars                      | %Disc | %Depr | Amount    |
|-----|-----|----------|----------------------------------|-------|-------|-----------|
| 1   | 1   |          | *FRT BUMPER                      | 0.00  | 0.00  | *235.00 F |
| 2   | 1   |          | *FRT BUMPER RETAINER RH          | 0.00  | 0.00  | *35.00 F  |
| 3   | 1   |          | *FRT BUMPER RETAINER LH          | 0.00  | 0.00  | *35.00 F  |
| 4   | 1   |          | *FRT BUMPER REINFORCEMENT        | 0.00  | 0.00  | *165.00 F |
| 5   | 1   |          | *FRT BUMPER FOAM                 | 0.00  | 0.00  | *60.00 F  |
| 6   | 1   |          | *FRT BUMPER CTR GRILLE           | 0.00  | 0.00  | *75.00 F  |
| 7   | 1   |          | *FRT BUMPER UPPER GRILLE         | 0.00  | 0.00  | *200.00 F |
| 8   | 1   |          | *FRT BUMPER LOWER GRILLE         | 0.00  | 0.00  | *105.00 F |
| 9   | 1   |          | *FRT BUMPER SIDE COVER RH        | 0.00  | 0.00  | *75.00 F  |
| 10  | 1   |          | *FRT BUMPER SIDE COVER LH        | 0.00  | 0.00  | *75.00 F  |
| 11  | 1   |          | *BONNET                          | 0.00  | 0.00  | *385.00 F |
| 12  | 1   |          | *BONNET FRT SEAL                 | 0.00  | 0.00  | *45.00 F  |
| 13  | 1   |          | *BONNET HINGE RH                 | 0.00  | 0.00  | *50.00 F  |
| 14  | 1   |          | *BONNET HINGE LH                 | 0.00  | 0.00  | *50.00 F  |
| 15  | 1   |          | *BONNET INSULATOR                | 0.00  | 0.00  | *195.00 F |
| 16  | 1   |          | *BONNET LOCK                     | 0.00  | 0.00  | *90.00 F  |
| 17  | 1   |          | *FRT SUPPORT PANEL COMPLETE      | 0.00  | 0.00  | *395.00 F |
| 18  | 1   |          | *FRT SUPPORT PANEL UPPER GARNISH | 0.00  | 0.00  | *80.00 F  |
| 19  | 1   |          | *WIPER COWL PANEL                | 0.00  | 0.00  | *280.00 F |
| 20  | 1   |          | *FRT FENDER RH                   | 0.00  | 0.00  | *270.00 F |
| 21  | 1   |          | *FRT FENDER LH                   | 0.00  | 0.00  | *270.00 F |
| 22  | 1   |          | *FRT FENDER BRACKET RH           | 0.00  | 0.00  | *45.00 F  |
| 23  | 1   |          | *FRT FENDER BRACKET LH           | 0.00  | 0.00  | *45.00 F  |
| 24  | 1   |          | *FRT FENDER INNER COVER RH       | 0.00  | 0.00  | *105.00 F |
| 25  | 1   |          | *FRT FENDER INNER COVER LH       | 0.00  | 0.00  | *105.00 F |
| 26  | 1   |          | *HEADLAMP RH                     | 0.00  | 0.00  | *680.00 F |
| 27  | 1   |          | *HEADLAMP LH                     | 0.00  | 0.00  | *680.00 F |
| 28  | 1   |          | *FOG LAMP RH                     | 0.00  | 0.00  | *125.00 F |
| 29  | 1   |          | *FOG LAMP LH                     | 0.00  | 0.00  | *125.00 F |
| 30  | 1   |          | *RADIATOR ASSY                   | 0.00  | 0.00  | *520.00 F |
| 31  | 1   |          | *CONDENSOR ASSY                  | 0.00  | 0.00  | *530.00 F |
| 32  | 1   |          | *FAN SHROUD                      | 0.00  | 0.00  | *145.00 F |
| 33  | 1   |          | *FAN MOTOR                       | 0.00  | 0.00  | *210.00 F |
| 34  | 1   |          | *FAN BLADE                       | 0.00  | 0.00  | *90.00 F  |
| 35  | 1   |          | *DISCHARGE HOSE                  | 0.00  | 0.00  | *265.00 F |
| 36  | 1   |          | *SUCTION HOSE                    | 0.00  | 0.00  | *305.00 F |
| 37  | 1   |          | *AIR FILTER HOUSING COMPLETE     | 0.00  | 0.00  | *280.00 F |
| 38  | 1   |          | *AIR FILTER DUCT                 | 0.00  | 0.00  | *85.00 F  |
| 39  | 1   |          | *WIPER PANEL END GARNISH RH      | 0.00  | 0.00  | *55.00 F  |
| 40  | 1   |          | *WIPER PANEL END GARNISH LH      | 0.00  | 0.00  | *55.00 F  |
| 41  | 1   |          | *FENDER REAR END COVER RH        | 0.00  | 0.00  | *50.00 F  |
| 42  | 1   |          | *FENDER REAR END COVER LH        | 0.00  | 0.00  | *50.00 F  |

F=Franchise part.

|                                            |                 |
|--------------------------------------------|-----------------|
| <b>Sub Total (\$\$)</b>                    | <b>7,720.00</b> |
| <b>+ Margin on L,N Items 10.00% (\$\$)</b> | <b>772.00</b>   |
| <b>Total Parts (\$\$)</b>                  | <b>8,492.00</b> |



## Estimates on Miscellaneous Items

| No                         | Qty | Particulars                                                   | Amount        |
|----------------------------|-----|---------------------------------------------------------------|---------------|
| <u>Miscellaneous Items</u> |     |                                                               |               |
| 1                          | 1   | CAR PLATE FRAME                                               | 30.00         |
| 2                          | 1   | FRONT BUMPER, FENDER INNER COVER & GRILLE GARNISH/PANEL CLIPS | 200.00        |
| 3                          | 1   | FRT CAR PLATE                                                 | 30.00         |
| <b>Sub Total (S\$)</b>     |     |                                                               | <b>260.00</b> |

## Estimates on Labour

| No                             | Particulars                                                                     | Lab.Type | Amount          |
|--------------------------------|---------------------------------------------------------------------------------|----------|-----------------|
| <u>Labour Items</u>            |                                                                                 |          |                 |
| 1                              | BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA                      | New      | 1,400.00        |
| 2                              | SPRAY PAINT - FRT BUMPER, BONNET X2, FRT FENDER X2, FRT DOOR X2 & SUPPORT PANEL | New      | 1,400.00        |
| 3                              | REFILL - RADIATOR COOLANT                                                       | New      | 80.00           |
| 4                              | REFILL - AIR COND GAS                                                           | New      | 80.00           |
| 5                              | ALIGN HEADLAMP/FOG LAMP & TEST WIRING                                           | New      | 80.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                                 |          | <b>3,040.00</b> |

Ding Auto Pte Ltd/SLN3344Y/14/02/2023 17:57. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >