# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897

LKK Auto Consultants Pte Ltd From: 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: JANICE KOH 03 Mar 2023 Date:

## **Preliminary Advice**

Vehicle No : SLN3344Y Accident Date : 14/02/2023 : TOYOTA COROLLA ALTIS Policy No. Make : SP2002589079 Assignment Date : 14/02/2023 **Excess** : S\$2,000.00 Date of Inspection : 17/02/2023 Est. Duration of Repair : 6 DAYS

Inspection At : DING AUTO PTE LTD

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,097.00 (Est \$11,792.00 + Supp \$1,305.00)
Revised Amount	:S\$	8,011.50 (Inc Supp \$1,205.00)
Check Items (Estimated)	:S\$	2,970.00
Total	:S\$	10,981.50

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	35,576.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,424.00

### Remarks

( )	<b>(</b> )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Kindly approve on Supplementary item.