

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2002589079	Date of Loss:	14/02/2023
Vehicle Reg. No.:	SLN3344Y	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TRILLIUM LEASING PTE LTD	Contact No:	+6591182220
Driver:	TAN YEN YANG		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Vehicle Reg. Date:	19/04/2017
Vehicle Colour:	Red		
Engine No:	1ZRY343115	Chassis No:	MR053REH104561394
Odometer:	237554 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Present Location:	DING AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	8,492.00
Miscellaneous Items	260.00
Labour	3,040.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	11,792.00
+ GST 8.00% (\$\$)	943.36
Nett Amount (\$\$)	12,735.36

This claim is handled by: **HENRY LEE YOON SANG**Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Feb 2023)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ding Auto Pte Ltd/SLN3344Y/14/02/2023 17:57

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	0.00	0.00	*235.00 F
2	1		*FRT BUMPER RETAINER RH	0.00	0.00	*35.00 F
3	1		*FRT BUMPER RETAINER LH	0.00	0.00	*35.00 F
4	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*165.00 F
5	1		*FRT BUMPER FOAM	0.00	0.00	*60.00 F
6	1		*FRT BUMPER CTR GRILLE	0.00	0.00	*75.00 F
7	1		*FRT BUMPER UPPER GRILLE	0.00	0.00	*200.00 F
8	1		*FRT BUMPER LOWER GRILLE	0.00	0.00	*105.00 F
9	1		*FRT BUMPER SIDE COVER RH	0.00	0.00	*75.00 F
10	1		*FRT BUMPER SIDE COVER LH	0.00	0.00	*75.00 F
11	1		*BONNET	0.00	0.00	*385.00 F
12	1		*BONNET FRT SEAL	0.00	0.00	*45.00 F
13	1		*BONNET HINGE RH	0.00	0.00	*50.00 F
14	1		*BONNET HINGE LH	0.00	0.00	*50.00 F
15	1		*BONNET INSULATOR	0.00	0.00	*195.00 F
16	1		*BONNET LOCK	0.00	0.00	*90.00 F
17	1		*FRT SUPPORT PANEL COMPLETE	0.00	0.00	*395.00 F
18	1		*FRT SUPPORT PANEL UPPER GARNISH	0.00	0.00	*80.00 F
19	1		*WIPER COWL PANEL	0.00	0.00	*280.00 F
20	1		*FRT FENDER RH	0.00	0.00	*270.00 F
21	1		*FRT FENDER LH	0.00	0.00	*270.00 F
22	1		*FRT FENDER BRACKET RH	0.00	0.00	*45.00 F
23	1		*FRT FENDER BRACKET LH	0.00	0.00	*45.00 F
24	1		*FRT FENDER INNER COVER RH	0.00	0.00	*105.00 F
25	1		*FRT FENDER INNER COVER LH	0.00	0.00	*105.00 F
26	1		*HEADLAMP RH	0.00	0.00	*680.00 F
27	1		*HEADLAMP LH	0.00	0.00	*680.00 F
28	1		*FOG LAMP RH	0.00	0.00	*125.00 F
29	1		*FOG LAMP LH	0.00	0.00	*125.00 F
30	1		*RADIATOR ASSY	0.00	0.00	*520.00 F
31	1		*CONDENSOR ASSY	0.00	0.00	*530.00 F
32	1		*FAN SHROUD	0.00	0.00	*145.00 F
33	1		*FAN MOTOR	0.00	0.00	*210.00 F
34	1		*FAN BLADE	0.00	0.00	*90.00 F
35	1		*DISCHARGE HOSE	0.00	0.00	*265.00 F
36	1		*SUCTION HOSE	0.00	0.00	*305.00 F
37	1		*AIR FILTER HOUSING COMPLETE	0.00	0.00	*280.00 F
38	1		*AIR FILTER DUCT	0.00	0.00	*85.00 F
39	1		*WIPER PANEL END GARNISH RH	0.00	0.00	*55.00 F
40	1		*WIPER PANEL END GARNISH LH	0.00	0.00	*55.00 F
41	1		*FENDER REAR END COVER RH	0.00	0.00	*50.00 F
42	1		*FENDER REAR END COVER LH	0.00	0.00	*50.00 F

F=Franchise part.

Sub Total (\$\$)	7,720.00
+ Margin on L,N Items 10.00% (\$\$)	772.00
Total Parts (\$\$)	8,492.00

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	CAR PLATE FRAME	30.00
2	1	FRONT BUMPER, FENDER INNER COVER & GRILLE GARNISH/PANEL CLIPS	200.00
3	1	FRT CAR PLATE	30.00
Sub Total (S\$)			260.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,400.00
2	SPRAY PAINT - FRT BUMPER, BONNET X2, FRT FENDER X2, FRT DOOR X2 & SUPPORT PANEL	New	1,400.00
3	REFILL - RADIATOR COOLANT	New	80.00
4	REFILL - AIR COND GAS	New	80.00
5	ALIGN HEADLAMP/FOG LAMP & TEST WIRING	New	80.00
Gross Labour Cost (S\$)			3,040.00

Ding Auto Pte Ltd/SLN3344Y/14/02/2023 17:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >