

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ng Pei Sze Stacey

Date: 17 Mar 2023

Preliminary Advice

Insured Vehicle No	: SMY4983B	Accident Date	: 13/02/2023
TP Vehicle No	: SHD6701E	Assignment Date	: 14/02/2023
Make	: MERCEDES-BENZ E220	Est. Duration of Repair	: 7
Date of Inspection	: 15/02/2023		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,094.92
Revised Amount	:S\$	9,283.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,283.44
 Lump Sum Repair	 :S\$	 6,600.00

Total Loss Consideration

New for Old Value	:S\$	
Book Value	:S\$	39,450.39
COE / PARF Rebate	:S\$	35,453.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,997.39

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please take note that the repair cost exceeding margin for repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.