

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: HL Assurance Pte Ltd  
11 Keppel Road  
#11-01 ABI Plaza  
Singapore 089057From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Grace Ng Tian Ai

Date: 17 Feb 2023

**Preliminary Advice**

Vehicle No	: SLM5514R	Accident Date	: 11/02/2023
Make	: NISSAN QASHQAI	Policy No.	: MP309471
Assignment Date	: 15/02/2023	Excess	: S\$300.00
Date of Inspection	: 16/02/2023	Est. Duration of Repair	: 6 DAYS
Inspection At	: WAH HONG MOTORS & CREDIT PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,988.25
Revised Amount	:S\$	5,193.00
Check Items (Estimated)	:S\$	1,762.50
Total	:S\$	6,955.50

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	30,925.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,075.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.