

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC2045Y

Make : HYUNDAI

Model : IONIQ(G2)

Date: 13/02/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER <i>Scr R</i>			\$ 481.10
10	FRT BUMPER CLIPS <i>XNN</i>			\$ 22.00
1	FRT BUMPER SIDE BRACKET LH <i>? X</i>			\$ 28.00
1	FRT WHEEL HUB CAP LH <i>Scr</i>			\$ 346.40
1	FRT FENDER LH <i>Scr R</i>			\$ 500.00
1	EMBLEM- BLUE DRIVE LH <i>mlc</i>			\$ 26.60
1	HEADLAMP LH <i>? X</i>			\$ 2,110.30
1	FRT BUMPER SIDE MOULDING LH <i>? X</i>			\$ 93.00
1	DAY LIGHT RH <i>? X</i>			\$ 642.50
1	FRT DOOR OUTER MOULDING LH <i>Scr</i>			\$ 110.10
	SUB TOTAL			\$ 4,449.40
	LESS 20%			\$ 889.88
	DISCOUNTED TOTAL			\$ 3,559.52
				<i>483.10</i>
				<i>96.62</i>
				<i>386.48</i>
	FRT DOOR COMFORT LOGO STICKER LH <i>mlc</i>			\$ 75.00
				\$ 75.00
				nett
	Labour Charge			
	PANEL BEATING		\$ 800.00	<i>700</i>
	SPRAY PAINTING CHARGE		\$ 1,000.00	<i>750</i>
	CHECK ALL LIGHTING		\$ 60.00	<i>30</i>
	TUFF KOTE		\$ 60.00	<i>XNN</i>
	TOTAL LABOUR		\$ 1,920.00	
	ESTIMATE TOTAL		\$ 5,554.52	<i>1941.48</i>
				<i>207 - 388.29</i>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				<i>= 1553.18</i>

*3 days L/S**~1550*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

14/2/23
830 am