

REPAIR ESTIMATE

LKK -

DATE: 13.02.2023INSURANCE: INCOME CHSMODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHC1096G

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper <i>for R</i>	1		\$ 459.40
	Rear Bumper Reinforcement <i>?X</i>	1		\$ 394.80
	Rear Bumper Reinforcement Brkt RH / LH <i>?X</i>	2	\$ 55.80	\$ 111.60
	Rear Bumper Centre Moulding <i>crn</i>	1		\$ 451.25
	Rear Bumper Cover Clips <i>XNN</i>	10	\$ 2.20	\$ 22.00
	Rear Bumper Tow Cover <i>XNN</i>	1		\$ 98.80
	Rear Bumper Fog Lamp <i>?X</i>	1		\$ 201.50
	Rear Smart Key Antenna <i>?X</i>	1		\$ 40.50
	SUB TOTAL			\$ 1,779.85
	LESS 20%			\$ 355.97
	DISCOUNTED TOTAL			\$ 1,423.88
	Reverse Sensor <i>?X NN</i>	1		\$ 180.00
	Rear No. Plate With Trim Cover <i>crn</i>	1		\$ 55.00
	SUB S/NETT			\$ 235.00
	LESS 10%			\$ 23.50
	S/NETT TOTAL			\$ 211.50
	Rear Fender Adv. Sticker RH / LH <i>3 ncc</i>	2	\$ 100.00	\$ 200.00
	Rear Bumper Mat	1		\$ 50.00
	SPARE PARTS TOTAL			\$ 1,885.38
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 2,705.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.

- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: