

MFORTDELGRO ENGINEERING PTE LTD

PAIR ESTIMATE*

VEHICLE NO SH7718A
MAKE HYUNDAI
MODEL IONIQ

DATE: 14.02.23
MVA JUMANI
DOA: 13.02.23

CL/Sum)
INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT DOOR OUTER HANDLE LH Scr R			\$234.80 R
1	FRT FENDER LH Dent ✓			\$588.80 ✓
1	FRT FENDER EMBLEM LH Nec ✓			\$26.60 ✓
1	FRT BUMPER SIDE BRACKET LH ?			\$35.00 X MN
1	FRT DOOR ASSY LH Dent ✓			\$1,797.20 ✓
1	REAR DOOR ASSY LH Scr R			\$2,117.90 R
1	REAR FENDER LH Dent x R			\$1,768.30 R
1	REAR BUMPER ASSY Scr R			\$459.40 R
1	FRT DOOR PROTECTOR LH Scr ? R			\$186.20 R
1	REAR DOOR PROTECTOR LH Scr ? R			\$166.20 R
	SUB TOTAL		2412.60	\$7,380.40
	LESS 20%		482.52	\$1,476.08
	DISCOUNTED TOTAL			\$5,904.32
	FRT DOOR COMFORT LOGO nec			\$75.00 NET ✓
	REAR DOOR APPS LOGO Nec			\$80.00 NET ✓
	REAR BUMPER MAT Nec			\$50.00 NET ✓
	PATROL STICKER nec			\$30.00 NET ✓
				\$235.00
	Labour Charge			
	PANEL BEATING			\$1,500.00 1400
	SPRAY PAINT			\$1,500.00 1250
	CHECK WIRING			\$50.00 30
	TUFF KOTE			\$50.00 X MN
	REMOVE/REFIX UPHOLSEY REAR			\$120.00 60
	ADVERTISEMENT LOGO-DOOR			\$200.00 NEC ✓
	ADVERTISEMENT LOGO-FENDER			\$200.00 NEC ✓
	TOTAL LABOUR			\$3,620.00 3140
	ESTIMATE TOTAL			\$6,759.32 5305.08
				20/- 1061.01
				FT= 4 244.06
				≈ 4250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal implications should arise from this estimate
- Subsequent repairs after the resurvey and is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date:

5 days L/S

17th 14/2/23
930am