



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 2759C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT V COWLING	CRACKED	156.00	156.00
1	LH HEADLIGHT	CRACKED	890.00	890.00
1	FRONT LH COWLING	CRACKED	786.00	786.00
1	FRONT LH SIGNAL LIGHT (LOWER)	BROKEN	245.00	245.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	311.00	-
1	LED SHIELD	CUT	786.00	786.00
1	FOOTMAT STAY LH	BENT	257.00	257.00
1	INNER COVER	CRACKED	488.00	488.00
1	LH MIRROR ASSY	BROKEN	439.00	439.00
1	LH MIRROR BRACKET	* CHECK	122.00	-
1	LH MIRROR BRACKET COVER (RUBBER)	TORN	42.00	42.00
1	LH LEVER	CRACKED	145.00	145.00
1	SET HANDLE BAR END L&R	CUT	122.00	122.00
1	IGNITON KEY SWITCH PANEL COVER	CUT	185.00	185.00
1	FRONT INNER FENDER	* CHECK	112.00	-
1	LH FOOTMAT COWLING	TORN	267.00	267.00
1	RH FOOTMAT COWLING	* CHECK	340.00	-
1	LH PILLION FOOTMAT STAY	BENT	183.00	183.00
1	LH PILLION FOOTMAT COVER	TORN	183.00	183.00
1	MAIN STAND	CUT	380.00	380.00
1	PILLION HANDLE	CUT	364.00	364.00
1	REAR LH COWLING (BIG)	TO REPAIR SEE LABOUR	695.00	-
1	REAR LH COWLING (SMALL)	CUT	65.00	65.00
1	LH TRANSMISSION COVER	CUT	176.00	176.00
1	PILLION BACKREST (NPA)	* CHECK	-	-
	LESS 10% DISCOUNT		-	-615.90
			7,739.00	5,543.10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	STEERING CONE & BEARING (SN)	NOT NECESSARY	120.00	-
			120.00	-
	LABOUR			
	FRONT FORK ALIGNMENT.		220.00	80.00
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	FRAME ALIGNMENT.	* CHECK	200.00	-
	WORKMANSHIP TO RENEW DAMAGE PARTS & AREAS. INCLUSIVE OF THE REPAIR OF FRONT FENDER AND REAR LH COWLING (BIG).		350.00	350.00
			890.00	430.00
	GRAND TOTAL		8,749.00	5,973.10
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$716.60 NETT)			5,973.10

Report Ref No. CS/SMR23001679/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.