

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

16 Feb 2023

Estimate No. : b1 64902

Page No. : 1 of 4

Date Estimated : 06/02/2023

Prepared By : Jack Ng Guo Ming

- ESTIMATE REPAIR FOR -

Ang Kirk Gine
79, Pasir Ris Grove#03-42

ACCOUNT - 40000

Cash Sales - Service
Singapore

Singapore 518209

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP5710M	WBA6V120405N97622	30/09/2019	216i Gran Tourer	17506

DESCRIPTION

To replace rear bumper and all damage parts.

To respray rear bumper

To check electrical wiring

Sundries.

VALUE

✓ 850 1,700.00

✓ 986 1,038.00

✓ 168 17.00

✓ 80 ? 150.00

Total Labour 1: 3,065.00

DESCRIPTION

REAR BUMPER PANEL PRIMED (LINES PDC) ✓

REAR BUMPER TRIM STRIP CHROM ? ✓

QTY

PRIC

VALUE

1 1,088.30

1,088.30

1 97.90

97.90

Total Parts : 1,186.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



Rasue

Hp 9000068

3 days

21/03/23 @ 1520

Resy before paint

Labour 1 : 3,065.00

Parts : 1,186.20

Labour 2 : 0.00

Excess : 0.00

Total GST @ 8% : 340.10

Grand Total : 4,591.30

THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **