



Final Report

Estimate No. : **b1 64902**
Date Estimated : **06/02/2023**
Prepared By : **Jack Ng Guo Ming**

Page No. :

- **ESTIMATE REPAIR FOR** -
Ang Kirk Gine
79, Pasir Ris Grove#03-42

- **ACCOUNT** - **303**
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 518209

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMP5710M	WBA6V120405N97622	30/09/2019	216i Gran Tourer	17506

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachment include carrying out necessary repairs caused by the accident	850.00		850.00
To respray rear bumper	986.00		986.00
To check electrical wiring and lightings at the rear section for proper function	168.00		168.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (LINES PDC)	1,088.30	1.00	0.00	1,088.30
REAR BUMPER TRIM STRIP CHROM	97.90	1.00	0.00	97.90

SUPPLEMENTARY ITEMS

Total Labour :	2,084.00
Total Parts :	1,186.20
Total Labour & Parts (before GST) :	3,270.20
Deduction for Excess :	
Total Repair Costs less Excess:	3,270.20
GST @8%:	261.62
Grand Total :	3,531.82

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

