

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK -

DATE: 13.02.2023INSURANCE: INCOME (LKS)MODEL: Hyundai i40 (FRONT & REAR)MVA: LIM T SVEHICLE NO.: SHD3584X

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper (ra)	1		\$ 1,052.20
	Front Bumper Clips NEC	10	\$ 2.20	\$ 22.00
	Front Bumper Upper Brkt RH	1		\$ 22.40
	Front Fender RH	1		\$ 663.00
	HeadLamp RH	1		\$ 1,388.00
	Radiator Grille (ra)	1		\$ 1,480.00
	Radiator Grille H Emblem	1		\$ 429.50
	Rear Bumper	1		\$ 553.00
	Rear Bumper Under Cover	1		\$ 228.00
	Rear Bumper Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Reinforcement	1		\$ 428.40
	Rear Bumper Rein-Brkt RH / LH	2	\$ 80.30	\$ 160.60
	SUB TOTAL			\$ 6,149.10
	LESS 20%			\$ 1,229.82
	DISCOUNTED TOTAL			\$ 4,919.28
	Front No. Plate With Trim Cover	1		\$ 75.00
	Reverse Sensors	1		\$ 135.70
	S/NETT SUB			\$ 210.70
	LESS 10%			\$ 21.07
	S/NETT TOTAL			\$ 189.63
	Front Fender Adv. Sticker RH	1		\$ 100.00
	Rear Fender Adv. Sticker RH / LH	2	\$ 100.00	\$ 200.00
	Rear Bumper Adv. Sticker	1		\$ 50.00
	SPARE PARTS TOTAL			\$ 5,458.91
	Labour Charge			
	Panel Beating			\$ 900.00
	Spray Painting Charge			\$ 900.00
	check lighting			\$ 40.00
	Tuff Weld			\$ 40.00
	TOTAL LABOUR			\$ 1,880.00
	ESTIMATE TOTAL			\$ 7,338.91

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Surveyor appointed by the insurance company.

Signature:
Date:

Total = 5843.98

-20% = 4675.18
Lump Sum: 4650.00

5 days LIS amount
14/2/23