

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23001685/UPA3Q2**Date:** 23/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900091099
Claimant Vehicle No :	FBS9978X	Insured Vehicle No :	SMK5036C
Date of Loss:	11/02/2023	Nature of Claim:	TP
		Claim No:	4247819257SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBS9978X	Engine No:	G3R9E001214
Make & Model:	YAMAHA T155, 155cc	Chassis No:	RLCUG1610MY001213
Reg. Date:	06/10/2021 (Man. Year: 2021)	Odometer:	11255 km
Colour:	Grey/Yellow		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80-90-17	Rear Tyre Size:	120-70-17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,527.30	2,868.80	1,658.50	36.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	280.00	640.00	69.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,447.30	3,148.80	2,298.50	42.20
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
+ Other Costs (S\$)		70.00		
Nett Liability (S\$)		3,278.80		
Global Sum Settlement (S\$)		3,270.00		

INSPECTION

Date of Assignment:	15/02/2023	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
Date Inspected:	15/02/2023 Inspected At:	1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Estimated Period of Repair:	3.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Bent / Twisted	640.00 FL	*580.00 FL
2	1		*FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
3	1		*FRONT RIM	Warped / Dented	385.00 FL	*300.00 FL
4	1		*FRONT RIM BEARING	Necessary	90.00 FL	*60.00 FL
5	1		*FRONT RIM SHAFT	Bent	75.00 FL	*62.00 FL
6	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
7	1		*HANDLE -BAR	Not Necessary	128.00 FL	*- FL
8	1		*HANDLE -BAR END	Not Necessary	136.00 FL	*- FL
9	1		*SET HAND GRIP	Not Necessary	68.00 FL	*- FL
10	1		*FRONT INNER COVER (KEY SIDE)	Cracked	170.00 FL	*145.00 FL
11	1		*LOWER HEADLAMP (LED)	Cracked	980.00 FL	*820.00 FL
12	1		*SIDE MIRROR	Not Necessary	128.00 FL	*- FL
13	1		*FRONT COVER -MATT	Cracked	215.00 FL	*150.00 FL
14	1		*SET FAIRING ASSY	Cracked	680.00 FL	*500.00 FL
15	1		*FRONT FOOTREST BRACKET	Not Necessary	186.00 FL	*- FL
16	2		*FRONT FOOTREST	Not Necessary	128.00 FL	*- FL
17	1		*GEAR PEDAL	Not Necessary	108.00 FL	*- FL
18	1		*BASKET	Bent	105.00 FL	*105.00 FL
19	1		*FRONT LOWER COVER	Cracked	125.00 FL	*125.00 FL
20	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
21	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
22	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
23	1		*SET STEERING CONE	Necessary	90.00 FS	*60.00 FS
24	1		*SET STICKER	Necessary	95.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,996.00	3,172.00
- List Item Discount on L Items 10.00/10.00% (S\$)	468.70	303.20
Total Parts (S\$)	4,527.30	2,868.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO PROVIDE LABOUR	New	420.00	280.00
3	TO REPAIR BODY FRAME	New	420.00	0.00
Gross Labour Cost (S\$)			920.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >