

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A1623001685/U293

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBS9978Xat Workshop m/s Eno Fire

of _____

Insured: SMK 5036C

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 614k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3 days

Res.: Yes or No

Lum Sum: 1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: LTA 37818

Vehicle: IN / OUT

118hVeh No: FBS9978XYr Regn: 06/10/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamahac.c. 155Colour: Grey / Yellow

A/C: Insured / Std / NI / NA

Sp. Reading: 11255

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RLCUG 1610MY 001213Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80-90-17R: 120-70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or maxxisFront 6Rear 6

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 11/01/23D.O.I. 15/2/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/2/23217 & 3148.80 inbound MR 200

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

P/P 3148.80

AIG

Owner : Abdul Hadi Bin Abdul Aziz
(88913558)

Accident Date : 11-Feb-23

Vehicle No : FBS9978X (COE051031)

Vehicle Model : Yamaha T155

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy <i>sent/1w</i>	\$ 580 640.00 <i>✓</i>
1	Fork under bracket <i>sent</i>	\$ 185.00 <i>✓</i>
1	Front rim <i>wapet/1P</i>	\$ 300 385.00 <i>✓</i>
1	Front rim bearing <i>ner</i>	\$ 60 90.00 <i>✓</i>
1	Front rim shaft <i>sent</i>	\$ 62 75.00 <i>✓</i>
1	Front brake disc <i>11</i>	\$ 155.00 <i>X</i>
1	Handle-bar <i>11</i>	\$ 128.00 <i>X</i>
1	Handle-bar end <i>11</i>	\$ 136.00 <i>X</i>
1	Hand grip (1 set) <i>11</i>	\$ 68.00 <i>X</i>
1	Front inner cover (key side) <i>Cne</i>	\$ 145 170.00 <i>✓</i>
1	Lower headlamp (LED) <i>Cne</i>	\$ 820 980.00 <i>✓</i>
1	Side mirror <i>11</i>	\$ 128.00 <i>X</i>
1	Front cover - matt <i>Cne</i>	\$ 150 215.00 <i>✓</i>
1	Fairing assy (1 set) <i>Cne</i>	\$ 500 680.00 <i>✓</i>
1	Front footrest bracket <i>11</i>	\$ 186.00 <i>X</i>
2	Front footrest <i>11</i>	\$ 128.00 <i>X</i>
1	Gear pedal <i>11</i>	\$ 108.00 <i>X</i>
1	Basket <i>sent</i>	\$ 105.00 <i>✓</i>
1	Front lower cover <i>4125 cne</i>	\$ 4,562.00
	Less 10%	\$ 456.20
		\$ 4,105.80

Special Net Items

1	Number plate (1 set) <i>11</i>	\$ 38.00 <i>X</i>
2	Fork oils <i>11</i>	\$ 30.00 <i>X</i>
2	Fork oil seals <i>11</i>	\$ 56.00 <i>X</i>
1	Steering cone (1 set) <i>ner</i>	\$ 90.00 <i>60</i>
1	Sticker (1 set) <i>ner</i>	\$ 95.00 <i>80</i>
		\$ 309.00

S/No. Labour

1	To provide towing service (LOD) S\$70.00	\$ -
2	To check wiring and reset headlamp focusing	\$ 11 80.00 <i>X</i>
3	To provide labour	\$ 420.00 <i>280</i>
4	To repair body frame	\$ 11 420.00 <i>X</i>
		\$ 920.00

\$ 5,334.80

Singapore Dollars: Five Thousand Three Hundred Thirty-Four and Cents: Eighty only

EROFIA MOTOR TRADING PTE LTD

Acknowledged by Repairer

Signature:

Page 1 of 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices must be resurveyed
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

P. 3032
112
2728.80
3148.80