

Case Details

Case Reference Number : TAX/01/23/2010
Type of Repair : Accident Repair
Vehicle Registration Number : SHB412P

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-20215-ID
Assigned By : Wei Siong #

Insurance Company Name : income insurance limited
Accident Date and Time : 06/01/2023 03:30 AM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, RR BUMPER ASSY	1	478.90	478.90	25.00	359.17	Replace	1	359.17	Replace	✓
Standard	Main			REAR BUMPER REINFORCEMENT	1	360.10	360.10	25.00	270.08	Replace	0	0.00	Not Give	XNN
Standard	Main			PAD, RR BUMPER, RH & LH , 1	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	✓
Standard	Main			PAD, RR BUMPER, RH & LH , 2	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	✓
Standard	Main			PAD, RR BUMPER, RH & LH , 3	2	4.30	8.60	25.00	6.45	Replace	2	6.45	Replace	✓
Standard	Main			PAD, RR BUMPER, CTR	3	2.50	7.50	25.00	5.63	Replace	3	5.63	Replace	✓
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	1	12.30	12.30	25.00	9.23	Replace	1	9.23	Replace	✓
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.80	4.80	25.00	3.60	Replace	0	0.00	Not Give	XNN
Standard	Main			RETAINER, RR BUMPER, LH	1	127.40	127.40	25.00	95.55	Replace	0	0.00	Check	?
Standard	Main			SEAL, RR BUMPER , LH	1	95.50	95.50	25.00	71.63	Replace	0	0.00	Not Give	XNN
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	✓
Standard	Main			GUARD, RR BUMPER, LOWER	1	623.50	623.50	25.00	467.63	Replace	1	467.63	Replace	✓
Standard	Main			FILLER, RR BUMPER , LH	1	168.60	168.60	25.00	126.45	Replace	1	126.45	Replace	✓
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0.00	Not Give	XNN
Standard	Main			ANTENNA, ELECTRICAL KEY	1	78.00	78.00	25.00	58.50	Replace	0	0.00	Not Give	XNN
Total Spare Part Cost									3,547.89	Surveyor Total		1,023.46		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00		
Final Spare Part Cost									2,838.31	Final Sur Total		818.77		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			REAR BUMPER GROMMET SCREW	1	2.20	2.20	25.00	1.65	Replace	0	0.00	Not Give	X NN
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	489.00	489.00	10.00	440.10	Replace	0	0.00	Check	?
Standard	Main			LENS & BODY ASSY, RR BUMPER, LH	1	544.40	544.40	10.00	489.96	Replace	0	0.00	Check	?
Standard	Main			COVER, REAR FLOOR UNDER, LH	1	261.60	261.60	25.00	196.20	Replace	0	0.00	Not Give	X NN
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	249.10	249.10	25.00	186.83	Replace	0	0.00	Not Give	X NN
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	707.10	707.10	25.00	530.33	Replace	0	0.00	Not Give	X NN
Total Spare Part Cost									3,547.89		Surveyor Total		1,023.46	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)			
Final Spare Part Cost									2,838.31		Final Sur Total		818.77	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION LH	676.00	200.00	
Total:			676.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200.00	
2	Main	TO RESPRAY REAR PANEL	180.00	0.00	X NN
3	Main	TO RESPRAY BUMPER BEAM	180.00	0.00	X NN
4	Main	TO RESPRAY REAR FENDER LH	378.00	200	
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0.00	X NN
Total:			500.00	80.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	30.00 ✓	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 XNN	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	50.00 ✓	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0.00 XNN	
Total:			500.00	80.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,838.31	818.77
Total Labour Cost	676.00	200.00
Total Spray Painting	1,116.00	400.00
Other	500.00	80.00
Overall Total	5,130.31	1,498.77
Lump Sum Repair Option	☒	☒
Lump Sum Total	5,150.00	1,500.00
Surveyor Approved Amount		1,500.00
No of Repair Days*	5	3
Remarks		LUMPSUM REPAIR / AFTER PAINT PHOTOS ,FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR IRFAN , HP 90097659 / EMAIL: irfan@lkkauto.com
Surveyor Name		Irfan
Signature		
		Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: