## DMFORTDELGRO ENGINEERING PTE LTD

**EPAIR ESTIMATE\*** 

/EHICLE NO

SH6232R

MAKE

REG. 25.08.2022

DATE

10.02.2023

CHIANG/INCOME

DEL	BYD Parts Description/ Labour	Туре	Unit Price	Amount
Qty	Parts Description/ Eastern			\$3,301.87
	1 REAR BUMPER COVER OPEN /		750.	79 \$ <del>2,013.7</del> 5
	1 REAR BUMPER LOWER COVER 5 0015			\$528.75
	1 REAR BUMPER REINFORCEMENT ? Z Z N		\$48.00	\$48.00
	1 REAR BUMPER REFLECTOR RH ? 7 4 10	Carolinasce	Marie Carlotte	\$375.00
	1 REAR BUMPER REVERSE LAMP 7 7	The second	\$87.00	\$174.00
	2 REAR BUMPER RETAINER LH/RH ? × J	AL	750.75	\$6,441.37
	LESS 20		150.15	\$1,288.27
	LESS 21	070	600.60	\$5,153.09
	REVERSE SENSOR Z X NN			\$240.00
	REAR BUMPER MAT IW		SAME TO SERVICE STATE OF THE S	\$50.00
	BUMPER LINE STICKER WCC			\$40.00
1	I BUIVIPER LINE STICKER & CC			\$330.00
Market and	Labour Charge			\$700.00
	Panel Beating			\$400.00
	Spray Painting Charge			\$60.00
	Tuff Coat			\$60.00
	Check Wiring		CALLERY TO SELECTION	\$1,220.00
on the last of	TOTAL LABOU	IR	-	\$1,ZZ0.00
	ESTIMATE TOTA	XC		\$6,703.09
1.	and the second s			
	LKK Auto Consultants hence notify the Repairer of the following:			
urer	To resurvey before/after spray painting		T	
	To display damaged part(s) during resurvey Parts prices are subject to confirmation	9		
Name You'd	Third party survey is on a "Without Prejudice" basis		1370-60	
	No illegal modification(s) is allowed			
4754 TA	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
To Mark	Acknowledged by Repairer		1	
	Signature:		1	
	Date:			
	This is an initial estimate based on a visual inspection of the prepared after the vehicle is surveyed by a motor Surv	he above vehicle	e. The final repair quan	tum wiii

2 drys PIP 1 Nan 13/2/23 410pm

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.03.2023

Time: 08:09:58 Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

**CUSTOMER: 7010045** 

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

305545338

**REGN NO** MILEAGE : SH 6232R

MAKE

: 0000000000

: BYD

MODEL

: NEW E6

DATE OF REGN

: 25.08.2022

DATE/TIME IN

: 10.02.2023 14:50

ACCIDENT DATE : 10.02.2023

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0401-0034-G REAR BUMPER LOWER BODY 1 750.75 20.00 600.60

SUB-TOTAL: 600.60

JOB NATURE

0000 PB

PANEL BEATING SH6232R TP

400.00

0001 SP

SPRAYPAINT CHARGE

400.00

0002 17-01

**CHECK ALL LIGHTING** 

30.00 50.00

0003 20-05

**REAR BUMPER MAT** 

40.00

0004 20-05

REAR BUMPER LINE STICKER

SUB-TOTAL: 920.00

TOTAL : 1,520.60

MVA NAME & SIGNATURE

AUTHORISED: YES/NO SURVEYOR NAME & SIGNATURE

DATE:

DATE: