

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
#01-49 SINGAPORE 415875
Tel: +65 64524457
Fax: +65 64524584
Company Reg No: 201929175W

Repair Estimate

Vehicle number: SNE1168B
Make & Model: Toyota Alphard
Chassis number: AGH300214237

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$	
1	Rear bumper <i>SCR</i>	1	\$ 1,314.00	1217 ✓
2	Rear bumper clips <i>X/V/V</i>	1set	\$ 80.00	
3	Rear bumper LH reflector ? <i>X nn</i>	1	\$ 189.00	
4	Rear bumper LH side retainer <i>X NN</i>	1	\$ 102.00	
5	Rear bumper LH upper cover <i>X nn</i>	1	\$ 342.00	
6	Rear bumper LH upper cover retainer <i>X nn</i>	1	\$ 163.00	
7	Rear LH fender <i>BVC</i>	1	\$ 1,218.00	✓
8	Rear LH fender glass with rubber moulding <i>ALL X nn</i>	1	\$ 783.00	
9	Rear LH fender lower protector <i>BR</i>	1	\$ 314.00	✓
10	Rear LH fender lower protector clips <i>NEC</i>	1set	\$ 40.00	20 ✓
11	Rear LH fender inner trim board <i>X nn</i>	1	\$ 537.00	
12	Rear LH fender inner trim board clips <i>X nn</i>	1set	\$ 80.00	
13	Rear LH fender inner air duct <i>X nn</i>	1	\$ 137.00	
14	Rear LH shock absorber <i>X nn</i>	1	\$ 109.00	
15	Rear LH lower arm <i>X nn</i>	1	\$ 687.00	
16	Rear LH knuckle arm <i>X nn</i>	1	\$ 622.00	
17	Rear LH upper arm <i>X nn</i>	1	\$ 746.00	
18	Rear LH trailing arm <i>X nn</i>	1	\$ 387.00	
19	Rear LH wheel bearing <i>X nn</i>	1	\$ 344.00	
20	Rear LH sliding door <i>BVC</i>	1	\$ 1,668.00	✓
21	Rear LH sliding door lower protector <i>missing</i>	1	\$ 879.00	✓
22	Rear LH sliding door lower protector clips <i>NEC</i>	1set	\$ 80.00	20 ✓
23	Rear LH sliding door outer chrome handle <i>X</i>	1	\$ 357.00	
24	Rear LH sliding door inner trim board <i>X ? ✓ BR</i>	1	\$ 1,413.00	1216 ✓
25	Rear LH sliding door inner trim board clips ? <i>X nn</i>	1set	\$ 80.00	
26	Rear LH sliding door glass regulator gear with motor ? <i>X nn</i>	1	\$ 589.00	
27	Rear LH sliding door lock <i>X nn</i>	1	\$ 556.00	
28	Rear LH sliding door rubber sensor ? <i>X nn</i>	1	\$ 1,009.00	
29	Rear LH sliding door weatherstrip <i>new nec</i>	1	\$ 367.00	✓
30	Front LH door <i>BVC</i>	1	\$ 1,499.00	✓
31	Front LH door outer chrome handle <i>X nn</i>	1	\$ 357.00	
32	Front LH door lower protector <i>missing</i>	1	\$ 712.00	✓
33	Front LH door lower protector clips <i>NEC</i>	1set	\$ 80.00	20 ✓
34	Front LH door lock <i>X nn</i>	1	\$ 556.00	
35	Front LH door inner trim board ? <i>✓ BR</i>	1	\$ 1,213.00	1092 ✓
36	Front LH door inner trim board clips ? <i>X nn</i>	1set	\$ 80.00	
37	Front LH door glass regulator gear with motor ? <i>X nn</i>	1	\$ 589.00	
38	Front LH door weatherstrip ? <i>X nn</i>	1	\$ 276.00	
39	LH side mirror assy <i>X nn</i>	1	\$ 1,327.00	
40	LH door centre pillar <i>dent R</i>	1	\$ 1,367.00	
41	Front LH fender <i>X nn</i>	1	\$ 1,089.00	
42	Front LH fender splash shield <i>X nn</i>	1	\$ 278.00	
43	Front LH fender splash shield clips <i>X nn</i>	1set	\$ 80.00	
44	Front bumper <i>X nn</i>	1	\$ 1,521.00	
45	Front bumper clips <i>X nn</i>	1set	\$ 80.00	

\$ 26,296.00
 Parts less 25% \$ 6,574.00
 Total \$ 19,722.00

10,242.00
 -25%
 7681.50

No.	Special Nett Items	Qty	Amount S\$
1	Rear LH fender glass sealant <i>nec</i>	1	\$ 80.00
2	Rear LH fender glass inner seal <i>nec</i>	1	\$ 60.00
3	Rear LH fender joint sealant <i>nec</i>	1	\$ 80.00
4	Rear LH sport rim <i>scr -</i>	1	\$ 1,250.00
5	Rear LH tyre <i>X nn</i>	1	\$ 580.00
6	Brake fluid <i>X nn</i>	1	\$ 80.00
7	Rear LH sliding door sun visor <i>X nn</i>	1	\$ 220.00
8	Front LH door sun visor <i>X nn</i>	1	\$ 220.00
Total:			\$ 2,570.00

40
 30
 50
 800

920

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,800.00
2	Spray painting on affected areas and panels	\$ 1,600.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 120.00
5	Remove and reinstall rear bumper reverse sensors to assist repair	\$ 100.00
6	Remove and replace rear LH fender glass to assist repair	\$ 280.00
7	Remove and reinstall roof lining, seats and carpet to assist repair	\$ 350.00
8	Remove and reinstall fuel tank pipes, hoses and sensors to assist repair	\$ 180.00
9	Test drive and adjust wheel alignment system	\$ 180.00
10	Remove and replace rear LH sliding door inner mechanism to new door	\$ 180.00
11	Remove and reinstall LH door pillar inner garnish and seat belts to assist repair	\$ 220.00
12	Remove and replace LH front door inner mechanism to new door	\$ 150.00
Total:		\$ 5,240.00

1000

1000

30

40

30

60

X

60

X

80

X

40

2340

Agreed Amount: _____ (Part by Part / Lump sum)
 Working days: _____

Spare Parts: \$ 19,722.00
 Special Nett: \$ 2,570.00
 Labour: \$ 5,240.00

10,941.50

L/S - 8753.20
 = 8750

Total Amount: \$ 27,532.00

7 days

L/S

17/12/23

330pm

154m