(08/11/13) Wef REF:	VCZ GIA
ADD. NEO. OT.	xx 1697 SV p3
ASSI	GNMENT
From:- Date:	Veh No: SHE 1168B Yr Regn: 1 2019
Estimated Cost	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SHE 1168B	Make: Toyota Alphand 2.55c CV T.o. 2493
at Werkshop m/s Bifficest	Colour Black A/C: Insured / Std / NI / NA
of	Sp.Reading 13381 T/Radio: Insured / Std / NI / NA
Insured: SMF 3358M	Eng/No:
Policy No. DMPCSNW00239192201	C/No: AGH 300 . 214237
Claims No. SNM23D201167/C02/TAYHP	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt-or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / SIRim / STD A/Rim or
	Tyre Size: F: 2H5 45 R 19
(Policy Condition)	R; "
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOIYOKO or continental
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 13/2/23 D.O.I. 17/2/23
Lum Sum: % · 3 Val.: Yes or No	Survey held at
	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
6/7/23 Lump Sum \$8750 confirmed by en	nail (Red 18,782, 68%)
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 7
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) 7/7/23-typist Add Fed	
	: Interview (\$) Photas
Report Format : Merimen	: Tech. Invs (\$) Others
Lump Sum / I.B.I. (\$ 8750	:Weekend (\$)

(08/11/13) wef

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 363D Vehicle Details

Vehicle No.: SNE1168B

Vehicle to be Exported: Yes

Intended Deregistration Date: 13 Feb 2023
Vehicle Make: TOYOTA

Vehicle Model: ALPHARD 2.5SC CVT

 Primary Colour:
 Black

 Manufacturing Year:
 2018

 Engine No.:
 2ARJ200199

 Chassis No.:
 AGH300214237

 Maximum Power Output:
 134.0 kW (179 bhp)

 Open Market Value:
 \$51,638.00

 Original Registration Date:
 25 Jan 2019

Original Registration Date: 25 Jan 2019
First Registration Date: 25 Jan 2019

Transfer Count: 1

Actual ARF Paid: \$64,949.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Jan 2029

PARF Rebate Amount: \$48,711.00

Intended COE Rebate Details
COE Expiry Date: 24 Jan 2029

COE Expiry Date: 24 Jan 2029
COE Category: E - Open - all except motorcycle

COE Period(Years): 10

QP Paid: \$32,909.00

COE Rebate Amount: \$19,146.00

Total Rebate Amount: \$67,857.00

The information contained herein is correct as at 13 Feb 2023

Date of Accident	: 13/2/27 Accident Time: 8:00 am (24-HR-FORMAT)
Accident Place	: 527 Any mo kin And 10
Vehicle Reg. No (Car plate No.)	SAEII68 B CC: 2500 Vehicle Make/Model: Toyota Alphari
Insurance Company	Chinh TAIVING Policy No. DMHCS NWBOOD PO2301
Name of Registered Owner	: Company/Individual Acron Gurk 728 Stag
ID of Registered Owner OWNER EMAIL ADDRESS:	: Co Reg No: Owner's NRIC No: \$8 5 2 8 3 63 D
AAron Quek. GC G gmail 120	: Co Contact No: Owner's Contact No: \$ 198 8 66
DRIVER'S Name	DRIVER'S NRIC No:
DRIVER'S Date of Birth	: 17 9 1685 DRIVER'S License Pass Date 15/2/13
Relationship bet. Owner & Driver	: Spouse \ Parents \Children\ Sibling \ Employee\ Others:
DRIVER'S Address	: 553 Any mo kio Are 10 403-1988 SISTOSS
DRIVER'S Contact No./ Alt No.	:1) 81988661 2)
DRIVER'S Occupation	: INDOOR \OUTDOOR (eg. working inside or outside of an ofc)
Email Address	: Aaron Quek. EC @ Small. com
Weather & Road Surface	: CLEAR & DRY \ RAINING & WET \AFTER RAIN & WET
Reporting Type	: Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (including Di Was the accident reported to the pol- Was there any video Captured by ca Exact purpose for which vehicle was Any injuries, if yes(name of the in	river):Name & Gender:
Other	Party Driver's Particulars (if any)
Vehicle Reg No: SMF 3358 M	Vehicle Reg No:
Vehicle Make\Model:	
Name DRIVER:	
IC No. DRIVER:	
DRIVER'S Contact & add:	DRIVER'S Contact & add:
REPORT FORM EXPLAINED IN : ENGLISH	/ CHN DSE / MALAY / TAMIL OTHERS:
WHO REPORTED THE ACCIDENT : OWNER	

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature Date & Time

Driver's Signature (if driver's not the policyholder) / Date

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

A SME HOSE

August Augu

	NAS	+1	rul	11/129		alon	5	th	-	61000	k	10	in the	rla	13.44	1.
21	NAS NO 1 RWILLE.	-	1	fery		6	1	ME	'/	PALL	5	NO	-f	5	114	IM
hill	2 6	_	ami		b h d		nom.		Hu	or de	m	1-1	1	111	(4/7)	
	while.									borte)	()	R	1	240	
-					-											
				-		-										
													-			
							-									
			-			-										
-		-				-										
						-	-									
												-				
WETE																

Policyholder's Signature 7 Date & Time

Driver's Rignature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SNE1168B Make & Model: Toyota Alphard Chassis number: AGH300214237 LIKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- » Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sinneluna

Date of survey: Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	A	mount S\$
1	Rear bumper 500	-	\$	1,314.00
2	Rear bumper clipsX/V/V	1set	\$	80,00
3	Rear bumper LH reflector 🤊	1	\$	189.00
4	Rear bumper LH side retainer & NN	-	\$	102.00
5	Rear bumper LH upper cover 🗸	1	\$	342.00
6	Rear bumper LH upper cover retainer 🗶		\$	163.00
7	Rear LH fender BUC	1	\$	1,218.00
8	Rear LH fender glass with rubber moulding	1	\$	783.00
9	Rear LH fender lower protector 3	1	\$	314.00
10	Rear LH fender lower protector clips /V/L C	1set	\$	40.00
11	Rear LH fender inner trim board X	1	\$	537.00
12	Rear LH fender inner trim board clips X	1set	\$	80.00
13	Rear LH fender inner air duct X	1	\$	137.00
14	Rear LH shock absorber X	1	\$	109.00
15	Rear LH lower arm 💉	1	\$	687,00
16	Rear LH knuckle arm X	1	\$	622.00
17	Rear LH upper arm	1	\$	746.00
18	Rear LH trailing arm	1	S	387.00
19	Rear LH wheel bearing	1	\$	344.00
20	Rear LH sliding door 130 C	1	\$	1,668.00
21	Rear LH sliding door lower protector missing	1	\$	879.00
22	Rear LH sliding door lower protector clips	1set	\$	80.00
23	Rear LH sliding door outer chrome handle X	1	\$	357.00
24	Rear LH sliding door inner trim board 🗶 ?	1	\$	1,413.00
25	Rear LH sliding door inner trim board clips ?	1set	\$	80.00
26	Rear LH sliding door glass regulator gear with motor 7	1	\$	589.00
27	Rear LH sliding door lock X	1	\$	556.00
28	Rear LH sliding door rubber sensor ?	1	\$	1,009.00
29	Rear LH sliding door weatherstrip	1	\$	367.00
30	Front LH door BUC	1	\$	1,499.00
31	Front LH door outer chrome handle 🗸	1	\$	357.00
32	Front LH door lower protector m. 550 4	1	\$	712.00
33	Front LH door lower protector clips wc -	1set	\$	80,00
34	Front LH door lock ×	1	\$	556.00
35	Front LH door inner trim board 7	1	\$	1,213,00
36	Front LH door inner trim board clips 7	1set	\$	80.00
37	Front LH door glass regulator gear with motor ?	1	\$	589.00
	Front LH door weatherstrip ?	1	\$	276.00
39	LH side mirror assy ✓	1	\$	1,327.00
	LH door centre pillar Den + R	1	\$	1,367.00
41	Front LH fender X	1	\$	1,089.00
42	Front LH fender splash shield X	1	\$	278.00
43	Front LH fender splash shield clips ×	1set	\$	80.00
44	Front bumper X	1	\$	1,521.00
45	Front bumper clips X	1set	\$	80.00

	\$ 26,296.00
Parts less 25%	\$ 6,574.00
Total	\$ 19,722.00

No.	Special Nett Items	Qty	A	mount S\$
1	Rear LH fender glass sealant		\$	80.00
2	Rear LH fender glass inner seal	1	\$	60.00
3	Rear LH fender joint sealant	1	\$	80.00
4	Rear LH sport rim Sur -	1	\$	1,250.00
5	Rear LH tyre 🗶		\$	580.00
6	Brake fluid X	1	\$	80.00
7	Rear LH sliding door sun visor 🗶	1 1	\$	220.00
8	Front LH door sun viosr		\$	220,00
		Total	\$	2,570.0

No. Amount S\$ Labour and painting 1.800.00 1000 Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas 2 Spray painting on affected areas and panels \$ 1,600.00 1000 30 3 Check wiring and lighting system on affected areas \$ 80.00 40 4 Apply rust coating chemical on affected areas and panels \$ 120.00 100.00 20 5 Remove and reinstall rear bumper reverse sensors to assis repair \$ 6 \$ 280.00 60 Remove and replace rear LH fender glass to assist repair 7 350.00 Remove and reinstall roof lining, seats and carpet to assist repair \$ 8 Remove and reinstall fuel tank pipes, hoses and sensors to assist repair \$ 180.00 60 180.00 入 9 Test drive and adjust wheel alignment system \$ 180.00 80 Remove and replace rear LH sliding door inner mechansim to new door 10 \$ 11 Remove and reinstall LH door pillar inner garnish and seat belts to assist repair \$ 220.00 X 150.00 40 12 Remove and replace LH front door inner mechansim to new door \$

Agreed Amount: (Part by Part / Lump sum) Working days:

> Spare Parts: \$ 19,722.00 2,570.00 5,240.00

\$

5,240.00

27,532.00

Total:

7 day Labour: \$
Total Amount: \$

17/7/2/23
330pm