

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/A15 23001699/4203

ASSIGNMENT

From: Date:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

13/3/23 4/5 & 6700 in hand Elin

Day 1/1/12.

C 3830
Vehicle: IN / OUT

17A & 16055

GBH 5347B Yr Regn: 29/06/18

(m)

Toyota Hiace

c.c 2982

white

A/C: Insured / Std / NI / NA

31/220

T/Radio: Insured / Std / NI / NA

SLR 92877

JTFHT02P100243604

Good / Fair / Poor / Burnt

In order / Jammed / Leaked / Burnt or

In order / Jammed / Leaked / Burnt or

Nil / S/Rim / STD A/Rim or

F: 195 R 15 Duraturn
R: 35

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

6 35

Rear

6

6

R/Bal.

mm

12/02/23

L/Bal.

mm

D.O.A.

15/02/23

N/S Int.



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

22 February 2023

not Authorised
her
15/2/23
4/5 @ 6700
6 days.

REG NO.: GBH 5347 B
MAKE/MODEL: TOYOTA HIACE

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front bonnet	\$ 844.50 X
2	Front bonnet hinges	\$ 77.00 X
1	Front bonnet lock	\$ 147.00 X
1	Front bonnet logo	\$ 68.50 80.70
1	Front bonnet rubber	\$ 121.10 X
1	Front corner panel	\$ 488.30
1	Front headlamp	\$ 945.10 1,700.20
1	Front bumper	\$ 681.10 700.30
1	Front bumper top beam	\$ 378.00 X
1	Front bumper bracket	\$ 96.65 X
1	Front bumper side grille	\$ 81.10 X
1	Front wire harness	\$ 382.70
1	Front bumper side retainer	\$ 121.10
1	Front bumper side bracket	\$ 48.95
1	Front door-LH	\$ 1,695.79
1	Front door checker	\$ 86.50
1	Front door glass outer moulding	\$ 131.70 X
2	Front door hinges	\$ 191.00
1	Front door inner board	\$ 811.10
1	Front door lock	\$ 321.10 X
1	Front door outer handle	\$ 171.10 X
1	Front door regulator motor	\$ 498.00 X
1	Front door glass stay	\$ 175.00 X
1	Front door rubber	\$ 190.05
1	Front door side mirror	\$ 747.90
1	Front door pillar-outer	\$ 855.50
1	Front step garnish	\$ 165.70
1	Front step panel	\$ 145.20
1	Front wheel rim	\$ 280.00 X
1	Front wheel cap	\$ 202.00 X
1	Front windscreen glass	\$ 1,179.48 X
1	Front windscreen moulding	\$ 96.78 X
		\$ 13,211.50
	Less 25%	\$ 3,302.88
		\$ 9,908.63

SPECIAL NETT ITEMS

1	Front door lettering sticker	115	121	\$	45.00	30
1	Front door company sticker	121		\$	500.00	450
1	Front tyre	11		\$	400.00	X
1	Front windscreen sealant	11		\$	50.00	X
				\$	995.00	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.		\$	80.00	20
2	To remove and refit front windscreen glass.	11	\$	180.00	X
3	To conduct wheel alignment.		\$	180.00	60
	To remove, refit door fittings and replace damaged parts, transfer all		\$	200.00	60
4	fittings to new door.				
5	To apply undercoating.		\$	200.00	80
6	Panel beating.		\$	1,500.00	1000
7	To re-spray painting on the affected areas.		\$	1,400.00	1000
			\$	3,740.00	

GRAND TOTAL :

\$ 14,643.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-7624-49

252

5718.36

480

2220

6418.36

202

6734