



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms LIM	Cust No/Name KCV09712/Ms LIM
16 CANBERRA DRIVE	Reg No/Reg Date SGY6688L*CS5P/ 19/11/201
#14-35	Date In/Mileage 10/05/2023/ 81082
SINGAPORE 768097	Chassis No MMBSTA13AJH004340
Contact No Mobile: 84181688	Engine No 3A92UHK0266
11/05/	Make/Model MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	12/05/2023/ 12:09	LER	972 / Mars Ler	14592			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT								
ACCIDENT ON 11/02/2023 ALONG JALAN MAS PUTEH								
OWNER CLAIMING THIRD PARTY								
LOSS OF USE 3 DAYS								
TP # SJU2841Y TP INS: ALLIANZ								
M SUNDRY								80.00
TO APPLY SEALANT KIT ON REAR BODY KIT								
E PNT88000								100.00
TO CHECK AND TEST REAR REVERSE SENSOR								
E PNT88000								640.00
TO REPLACE REAR BODY KIT,ETC								
-TO REPAIR REAR BUMPER								
STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS								
E PNT98000								550.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								
A 10028901								280.00
TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE CODE								
A 54900099								80.00
CHECK WIRING & ELECTRICAL SYSTEM								
M SUNDRY								30.00
SUNDRIES								
P BODYKITS					1.00	1643.00	00.00	1643.00
P CLIP,RR BUMPER					10.00	4.00	00.00	40.00

Confirm & accepted by

Finalization

8% GST on Nett 3,443.00 3,443.00

 275.44

Total Payable 3,718.44

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.