

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 17 Feb 2023

Preliminary Advice

Vehicle No	: SNA8769S	Accident Date	: 12/02/2023
Make	: KIA SORENTO	Policy No.	: SP2001882155-01
Assignment Date	: 15/02/2023	Excess	: S\$1,100.00
Date of Inspection	: 16/2/2023	Est. Duration of Repair	: 14
Inspection At	: CYCLE & CARRIAGE KIA PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	138,558.00
Revised Amount	:S\$	4,458.00
Check Items (Estimated)	:S\$	133,700.00
Total	:S\$	138,158.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	176,000.00
COE / PARF Rebate	:S\$	70,405.00
Salvage Value	:S\$	
Margin for Repair	:S\$	105,595.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer are unable to repair within the Nett Value
- Pending investigation