



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Ref No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TEO MARIE ELAINE	Cust No/Name LCV14309/TEO MARIE ELAINE
14 CORONATION RD WEST	Reg No/Reg Date SNA8769S / 21/07/202
SINGAPORE 269389	Date In/Mileage 13/02/2023/ 0
Contact No	Chassis No KNARH81BVM5110463
	Engine No D4HEMH289670
	Make/Model KIA/SORENTO 2.2 A D SX SR G899 TECH
	Colour/Trim M4B MINERAL BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV14309	CRDVCH	15/02/2023/ 12:25	COC	442 / CocoLu	64212			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E FNT88000								2560.00
REMOVE & INSTALL BUMPER, BONNET, FRT SUPPORT PANEL, REAR BUMPER?								640.00
A 90000001								640.00
CHECK WIRING & ELECTRICAL SYSTEM ✓								640.00
A 90000001								640.00
RENEW FRT UNDER CARRIAGE ?								640.00
A 90000001								1280.00
RENEW REAR UNDER CARRIAGE ?								380.00
A 90000001								1280.00
RENEW FLY WHEEL INCLUDE REMOVE TRANSMISSION ASSY ?								1000
A 10028901								640.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								1040.00
A 90000001								640.00
REMOVE & INSTALL CARPETS AND SEATS								1040.00
A 90000001								640.00
RENEW FLOOR WIRING ?								1040.00
A 90000001								640.00
REMOVE & INSTALL BOTH FRT DOORS AND BOTH REAR DOORS TRIMS, GLASS, ?								1280.00
SPEAKERS AND OTHER MECHANISMS								280.00
A 90000001								120.00
RENEW EXHAUST ASSY ?								640.00
A 90000001								320.00
RENEW ENGINE ASSY ?								380.00
M SUNDRY								
APPLY NEW ENGINE NUMBER FROM LTA ?								
B WHEELALIGNMENT120L								
To Conduct Computerize Full Wheel Alignment X								
A 90000001								
REMOVE & INSTALL DASHBOARD TO FACILITATE REPAIR ?								
A 90000001								
RENEW AUDIO SYSTEM ?								
A 90000001								
CALIBRATION 360 CAMERA ?								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before work commences.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TEO MARIE ELAINE 14 CORONATION RD WEST SINGAPORE 269389 Contact No	Cust No/Name	LCV14309/TEO MARIE ELAINE
	Reg No/Reg Date	SNA8769S / 21/07/202
	Date In/Mileage	13/02/2023/ 0
	Chassis No	KNARH81BVM5110463
	Engine No	D4HEMH289670
	Make/Model	KIA/SORENTO 2.2 A D SX SR G899 TECH
	Colour/Trim	M4B MINERAL BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV14309	CRDVCH	15/02/2023/ 12:25	COC	442 / CocoLu	64212

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A 90000001 TO CLEAN AND DRY UP CAR INNER FLOOR PANEL				640.00
M SUNDRY TOP UP AIRCON GAS?				80.00?
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR & RIADIATOR .				180.00?
A 90000001 CLEAN UP ADD BLUE TANK & FUEL TANK?				640.00?
A 90000001 TOP UP ADD BLUE LIQUID ?				150.00?
A 90000001 TOP UP COOLANT ?				200.00?
A 90000001 BLEEDING BRAKE SYSTEM AND CONDUCT BRAKE TEST				640.00?
A 90000001 TOP UP ENGINE OIL ?				230.00?
E PNT98000 SPRAY PAINT FOR FLOOR PANEL ?				550.00?
M SUNDRY MOTOR ASSY-FRONT POWER WDW,LH ?				202.00?
KS82450P2010				
M SUNDRY MOTOR ASSY-REAR POWER WDW,LH ?				286.00?
KS83450P2010				
M SUNDRY MOTOR ASSY-REAR POWER WDW,RH ?				286.00?
83460P2010				
M SUNDRY WIRING ASSY FRT DOOR RH ?				380.00?
KS91610P2210				
M SUNDRY WIRING ASSY FRT DOOR LH ?				380.00?
KS91600P2201				

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of breakage. The rubber seal or other repair material is the property of the customer.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TEO MARIE ELAINE	Cust No/Name	LCV14309/TEO MARIE ELAINE
14 CORONATION RD WEST	Reg No/Reg Date	SNA8769S / 21/07/202
SINGAPORE 269389	Date In/Mileage	13/02/2023/ 0
Contact No	Chassis No	KNARH81BVM5110463
	Engine No	D4HEMH289670
	Make/Model	KIA/SORENTO 2.2 A D SX SR G899 TECH
	Colour/Trim	M4B MINERAL BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV14309	CRDVCH	15/02/2023/ 12:25	COC	442 / CocoLu	64212			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								398.00?
WIRING ASSY REAR DOOR LH								398.00?
KS91620P2280								3800.00?
M SUNDRY								2650.00?
WIRING ASSY REAR DOOR LH								8600.00?
KS91630P2280								23786.00?
M SUNDRY								
BOOSTER ASSY BRAKE								
KS59110P2910								
M SUNDRY								
HYDRAULIC UNIT ASSY								
KS58910P2300								
M SUNDRY								
WIRING ASSY FLOOR								
91550P2481								
M SUNDRY								
ENGINE ASSY SUB								
1R3212RH00								
M SUNDRY								
MANIFOLD ASSY INTAKE								
KS283102R000								
M STRUT ASSY-FR,LH					1.00	419.00	00.00	419.00
M STRUT ASSY-FR,RH					1.00	419.00	00.00	419.00
M DAMPER ASSY-DYNAMIC					2.00	64.00	00.00	128.00
P SHOCK ABSORBER ASSY-REAR					2.00	264.00	00.00	528.00
P ULTRASONIC SENSOR ASSY-P.A.S					2.00	189.00	00.00	378.00
P ULTRASONIC SENSOR ASSY-P.A.S					2.00	171.00	00.00	342.00
M UNIT ASSY-FR VIEW CAMERA					1.00	472.00	00.00	472.00
P ULTRASONIC SENSOR ASSY-P.A.S					1.00	171.00	00.00	171.00
M ULTRASONIC SENSOR ASSY-P.A.S					3.00	171.00	00.00	513.00
M WIRING HARNESS-RR BUMPER					1.00	334.00	00.00	334.00
M ANTENNA ASSY-SMARTKEY					1.00	81.00	00.00	81.00
M UNIT ASSY-FRONT RADAR					1.00	1162.00	00.00	1162.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : HR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TEO MARIE ELAINE	Cust No/Name LCV14309/TEO MARIE ELAINE
14 CORONATION RD WEST	Reg No/Reg Date SNAB769S / 21/07/202
SINGAPORE 269389	Date In/Mileage 13/02/2023/ 0
Contact No	Chassis No KNARH81BVM5110463
	Engine No D4HEMH289670
	Make/Model KIA/SORENTO 2.2 A D SX SR G899 TECH
	Colour/Trim M4B MINERAL BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV14309	CRDVCH	15/02/2023/ 12:25	COC	442 / CocoLu	64212
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M MODULE ASSY-AIR BAG CONTROL		1.00	860.00	00.00	860.00
M UNIT ASSY-IBU		1.00	547.00	00.00	547.00
M ANTENNA ASSY-SMARTKEY		2.00	81.00	00.00	162.00
M BUZZER ASSY-PIEZO		1.00	58.00	00.00	58.00
M TRANSMISSION ASSY-DCT		1.00	16661.00	00.00	16661.00
P BEARING-REAR WHEEL		2.00	392.00	00.00	784.00
P HUB ASSY-FR WHEEL		1.00	460.00	00.00	460.00
M HUB ASSY-FR WHEEL		1.00	460.00	00.00	460.00
M SENSOR-NOX		1.00	1052.00	00.00	1052.00
M SENSOR-PM		1.00	1083.00	00.00	1083.00
M MUFFLER COMPLETE-CHMBR & CONVE		1.00	1747.00	00.00	1747.00
M MUFFLER ASSY-REAR		1.00	1107.00	00.00	1107.00
M STARTER ASSY		1.00	645.00	00.00	645.00
M SENSOR-AIR TEMPERATURE		1.00	26.00	00.00	26.00
M FILTER & COLLER ASSY-OIL		1.00	554.00	00.00	554.00
M PEDAL ASSY-ACCELERATOR		1.00	369.00	00.00	369.00
M UNIT ASSY-L.D.C		1.00	429.00	00.00	429.00
M CARPET ASSY-FLOOR -soaked-		1.00	1394.00	00.00	1394.00
M PAD-FRONT,LH		1.00	188.00	00.00	188.00
M PAD-FRONT,RH		1.00	188.00	00.00	188.00
M PAD-CENTER,RH		1.00	197.00	00.00	197.00
M CARPET ASSY-REAR FLOOR -soaked-		1.00	404.00	00.00	404.00
M ISOLATION PAD-FR TUNNEL		1.00	88.00	00.00	88.00
M PAD ASSY-REAR TUNNEL		1.00	163.00	00.00	163.00
M SPEAKER ASSY-FR DR		2.00	242.00	00.00	484.00
M SPEAKER ASSY-RR DR		2.00	242.00	00.00	484.00
M EXTERNAL AMP ASSY		1.00	2677.00	00.00	2677.00
M SPEAKER ASSY-SUB WOOFER		1.00	1180.00	00.00	1180.00
M SPEAKER ASSY-RR,RH		1.00	242.00	00.00	242.00
M SPEAKER ASSY-RR,LH		1.00	242.00	00.00	242.00
M BRAKE ASSY-RR WHEEL,LH		1.00	899.00	00.00	899.00
M BRAKE ASSY-RR WHEEL,RH		1.00	899.00	00.00	899.00
M MODULE-DOSING NOZZLE		1.00	689.00	00.00	689.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of repair. The rubber seal or other repair requiring the removal of the windscreen in the event of inadvertent breakage is the source of repair.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TEO MARIE ELAINE	Cust No/Name	LCV14309/TEO MARIE ELAINE
14 CORONATION RD WEST	Reg No/Reg Date	SNAB769S / 21/07/202
SINGAPORE 269389	Date In/Mileage	13/02/2023/ 0
Contact No	Chassis No	KNARHB18VM5110463
	Engine No	D4HEMH289670
	Make/Model	KIA/SORENTO 2.2 A D SX SR G899 TECH
	Colour/Trim	M4B MINERAL BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV14309	CRDVCH	15/02/2023/ 12:25	COC	442 / CocoLu	64212
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M CONTROL UNIT-DOSING		1.00	698.00	00.00	698.00
M LAMP ASSY-FR FOG,RH		1.00	646.00	00.00	646.00
M LAMP ASSY-FR FOG,LH		1.00	646.00	00.00	646.00
M WIRING HARNESS-FR BUMPER		1.00	371.00	00.00	371.00
M LAMP ASSY-REAR FOG & R/REFL,LH		1.00	127.00	00.00	127.00
M LAMP ASSY-REAR FOG		1.00	146.00	00.00	146.00
M MOTOR ASSY-FRONT POWER WDW,RH		1.00	202.00	00.00	202.00
M TRIM ASSY-LUGGAGE SIDE RH		1.00	518.00	00.00	518.00
M TRIM ASSY-LUGGAGE SIDE LH		1.00	420.00	00.00	420.00
M TCU		1.00	1303.00	00.00	1303.00
M LAMP ASSY-HEAD,RH		1.00	2279.00	00.00	2279.00
M LAMP ASSY-HEAD,LH		1.00	2279.00	00.00	2279.00
M RESERVOIR & PUMP ASSY-WASHER		1.00	190.00	00.00	190.00
M COMPRESSOR ASSY		1.00	1639.00	00.00	1639.00
M RR HTR & A/CON UNIT		1.00	1689.00	00.00	1689.00
M JOINT ASSY-STRG		1.00	443.00	00.00	443.00
M CYLINDER ASSY-BRAKE MASTER		1.00	500.00	00.00	500.00
M GEAR ASSY-STEERING		1.00	1179.00	00.00	1179.00
M SENSOR ASSY-WHEEL SPEED,RH		1.00	128.00	00.00	128.00
M SENSOR ASSY-WHEEL SPEED,LH		1.00	128.00	00.00	128.00
M CABLE ASSY-ABS.EXT,RH		1.00	194.00	00.00	194.00
M CABLE ASSY-ABS.EXT,LH		1.00	194.00	00.00	194.00
M CLUTCH ASSY-DOUBLE		1.00	2268.00	00.00	2268.00
M SHAFT ASSY-DRIVE,LH		1.00	1133.00	00.00	1133.00
M SHAFT ASSY-DRIVE,RH		1.00	1133.00	00.00	1133.00
M FILTER & COLLER ASSY-OIL		1.00	554.00	00.00	554.00
M PUMP ASSY-OIL		1.00	698.00	00.00	698.00
M BLOWER ASSY		1.00	698.00	00.00	698.00
M PIPE-EXHAUST,CTR		1.00	528.00	00.00	528.00
M MUFFLER ASSY-FRONT		1.00	366.00	00.00	366.00
M CONVERTER ASSY-CATALYTIC		1.00	6788.00	00.00	6788.00
M SENDER ASSY-FUEL PUMP		1.00	95.00	00.00	95.00
M PUMP ASSY-FUEL		1.00	583.00	00.00	583.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TEO MARIE ELAINE	Cust No/Name LCV14309/TEO MARIE ELAINE
14 CORONATION RD WEST	Reg No/Reg Date SNA8769S / 21/07/202
SINGAPORE 269389	Date In/Mileage 13/02/2023/ 0
Contact No	Chassis No KNARH81BVM5110463
	Engine No D4HEMH2B9670
	Make/Model KIA/SORENTO 2.2 A D SX SR G899 TECH
	Colour/Trim M4B MINERAL BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV14309	CRDVCH	15/02/2023/ 12:25	COC	442 / CocoLu	64212
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
M FILTER-AIR CLEANER	1.00	46.00	00.00	46.00	
M SENSOR ASSY-AIR FLOW	1.00	276.00	00.00	276.00	
M TURBOCHARGER	1.00	3738.00	00.00	3738.00	
M VALVE ASSY-AIR CONTROL	1.00	770.00	00.00	770.00	
M EGR COOLER	1.00	980.00	00.00	980.00	
M VALVE ASSY-EGR(A)	1.00	1001.00	00.00	1001.00	
M ELBOW ASSY-LP EGR VALVE	1.00	29.00	00.00	29.00	
M ALTERNATOR ASSY	1.00	1350.00	00.00	1350.00	

Estimate

R48UL
Hp 90010068

14 days

P/P

16/02/23 @ 1430

EXCESS: TBA

Repair

Res before repair

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	138,558.00
8% GST on	127013.00	10161.04
7% GST on	11545.00	808.15
Total Payable		149,527.19

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage to the windscreen. The rubber seal or other repair requiring the removal of the windscreen is the responsibility of the repairer.