

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 23 Feb 2023

Preliminary Advice

Vehicle No	: SJR8033P	Accident Date	: 11/02/2023
Make	: SUBARU FORESTER	Policy No.	: DMPG22013676
Assignment Date	: 15/02/2023	Excess	: S\$0.00
Date of Inspection	: 22/02/2023	Est. Duration of Repair	: 9 days
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,595.71
Revised Amount	:S\$	17,318.44
Check Items (Estimated)	:S\$	1,338.48
Total	:S\$	18,656.92

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	129,000.00
COE / PARF Rebate	:S\$	51,515.00
Salvage Value	:S\$	
Margin for Repair	:S\$	77,485.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Part by Part Repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.