

ORIMAGE ENTERPRISES PTE. LTD.
LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0058/2023
DATE : 15-FEB-2023

ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER THREE
S(038988)
TEL : 6829 9199/200
FAX : 6829 9248/49
MOTOR CLAIM DEPT

OWNER'S NAME : GAN CHEE MENG
ADDRESS : APT BLK 80C TELOK BLANGAH STREET 31
#26-131
S(103080)
TELEPHONE NO : 9677 6826

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : DMPG22013676 ERGO
VEHICLE NO : SJR8033P
MODEL CODE : SKEBKFL
MODEL/YEAR : FORESTER 2.0I-S EYESIGHT HYBRID AWD CVT
ENGINE NO : FB20UC74718
CHASSIS NO : JF1SKEKL5LG039566
MILEAGE : 1 KM
DATE IN : 15/02/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 15/02/2023

Print Date : 17/02/2023
Print Time : 10:58:14

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJR8033P

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	TYRE VALVE <i>ne/</i>	23142GA040	17.00			
2	PNL SD OUT QTR RPRH <i>4/</i>	51439SJ0009P	778.90			
3	FENDER F RH <i>bt</i>	57120SJ0009P	377.40			
4	BUMPER PUNCHING FEU <i>scu/</i>	57702SJ000	610.50			
5	BUMPER FACE REAR <i>scu/</i>	57704SJ310	610.50			
6	BRKT CORNER F RH <i>?</i>	57707SJ000	37.00			
7	BRKT SD F RH <i>ne/</i>	57707SJ021	14.80			
8	BRKT SD R RH <i>ne/</i>	57707SJ320	14.80			
9	PNL COMPL DR F RH <i>4/</i>	60009SJ0009P	884.30			
10	PNL COMPL DR R LH <i>bt/</i>	60409SJ0109P	801.80			
11	WDW GL ASSY R QTRRH <i>ne/ photo</i>	65209SJ040	551.30			
12	DAM RUBBER <i>ne/</i>	65245SJ000	17.80			
13	LAMP ASSY HEAD RH <i>cu/</i>	84002SJ020	2380.00			
14	LAMP ASSY TURN SDRH <i>?</i>	84401FL000	77.40			
15	LENS & BODY COMPLJPR <i>?</i>	84912SJ040	408.00			
16	COVER(RCL) RH <i>?</i>	84953SJ000	18.50			
17	RADAR ASSY <i>?</i>	87611SJ001	1110.00			
18	RADAR BRACKET RH <i>?</i>	87613SJ010	22.20			
19	CLIP BMPR *11PCS <i>ne/</i>	909140007	26.40			
20	CLIP *2PCS <i>ne/</i>	909140062	6.00			
21	R VIEW MIR UNIT RHR <i>X</i>	91036SJ080	619.80			
22	COVER CAP OUT MIRRH <i>X</i>	91054AL040	444.00			
23	COVER MIR BODY RH <i>X</i>	USE PDI STOCK LAST 4PCS 91054FL200	25.90			
24	GARNISH AY FENDERRH <i>X</i>	91112SJ200	133.20			
25	GARNISH AY DR R URH <i>X</i>	91112SJ300	111.00			

NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
26	GARNISH AY SD SL RH X	91112SJ320	111.00			
27	GARNISH AY R QTR RH ser	91112SJ340	101.80			
28	GARNISH AY DR F RRH X	91112SJ400	331.90			
29	GARNISH AY DR R RRH X	91112SJ420	177.60			
30	DISC WHEEL AL 18X8.0 (FORESTER I-S) at	LPHE16TMT10G	3000.00			
31	GT STICKER CTR CAP XV X	LPHGT28821VA011	11.10			
32	GT CTR CAP XV X	LPHGT28821VA012	37.00			
33	FRONT UNDER SPOILER GT-ML ser	LPHGT96020ES1	516.00			
34	SIDE UNDER SPOILER GT RH-ML X	LPHGT96031ES1-RH	399.99			
35	REAR UNDER SPOILER GT-ML X	LPHGT96050ES1	516.00			
SUB TOTAL			15300.89	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			3060.18	0.00	0.00	0.00
GRAND TOTAL			12240.71	0.00	0.00	0.00
OVERALL TOTAL			12240.71			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AGE ENTERPRISES PTE. LTD.
B KEE ROAD
ORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJR8033P

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 0DCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM) AGAINST OWN POLICY-ERGO INS		
2 ZZ/001	DOA:11/FEB/2023 TIME:1400 HRS LOCATION:KM 158 LEBUHRAYA PANTAI TIMUR,MALAYSIA		
3 ZZ/002	REPLACE FRT BUMPER,FRT RH FENDER,FRT RH DOOR,REAR RH DOOR,REAR RH QUARTER PANEL & REAR BUMPER @600x7	4900.00	4200
4 ZZ/003	RESPRAY FRT BUMPER,FRT RH FENDER,FRT RH DOOR,RR RH DOOR,RR QUARTER PANEL,RH SILL PANEL & RR BUMPER @500x6	4500.00	3120
5 ZZ/004	TO CONDUCT FRONT LIGHTING TEST	50.00	/
6 ZZ/005	TRANSFER FRONT DOOR MECHANISM	200.00	/
7 ZZ/006	TRANSFER REAR DOOR MECHANISM	200.00	/
8 ZZ/007	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	/
9 ZZ/008	REMOVE & RENEW REAR RH QUARTER GLASS	180.00	/
10 ZZ/009	TO SUPPLY & INSTALL REAR RH QUARTER GLASS SOLAR FILM	145.00	X
11 ZZ/011	TRANSFER/BALANCETY/RIMS (FRONT & REAR*RHS)	100.00	/
12 ZZ/012	4 WHEEL ALIGNMENT	200.00	171
13 ZZ/013	TRANSFER REVERSE SENSOR (OLD TO NEW)	100.00	80
14 ZZ/014	FAULT DIAGNOSTIC (RESET)	280.00	/
15 ZZ/015	SUNDRIES	100.00	20
16 ZZ/10	REMOVE & RENEW GT EDITION BODYKITS	200.00	X
TOTAL LABOUR CHARGES		11355.00	

COPY OF ESTIMATE FOR VEHICLE REGN NO SJR8033P

TOTAL LABOUR CHARGES	11355.00
TOTAL SPARE PARTS CHARGES	12240.71
GRAND TOTAL	23595.71 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Perse - 4p 90010068
SURVEYED DATE	:	22/02/23 @ 1030
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 9 days
LIABILITY	:	0.00
REMARKS	:	EXCESS: TBA
		Revert

Rey before print

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurer C

Acknowledged by Repairer
Signature:
Date: