

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123001714/UQY3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : FBP4247X **Insured Vehicle No :** SLP1156B

Date of Loss: 23/10/2022 Nature of Claim: TP Claim No: CDMPG22002857

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP4247X**

Make & Model: YAMAHA SNIPER T150, 150cc Engine No: G3E6E0484074

Reg. Date: 30/03/2019 (Man. Year: 2019) Chassis No: MH3UG0740K0152414

Colour: Blue Odometer: 89456 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80-90-17 Rear Tyre Size: 120-70-17

Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,316.20	946.60	2,369.60	71.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	250.00	630.00	71.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,196.20	1,196.60	2,999.60	71.48
Approved Total (Overridden) (S\$)		950.00		
Nett Amount (S\$)	4,196.20	950.00	3,246.20	77.36

INSPECTION

Date of Assignment: 15/02/2023

Date Inspected: 16/02/2023 Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 May 2023)	
Parts:	N/A	YAMAHA SNIPER T150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP4247X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL RIM	Not Necessary	385.00 FL	*- FL
2	1		*FRONT RIM SHAFT	Not Necessary	90.00 FL	*- FL
3	1		*FRONT RIM BEARING	Not Necessary	80.00 FL	*- FL
4	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
5	1		*HANDLE -BAR	Not Necessary	128.00 FL	*- FL
6	1		*HANDLE -BAR END (N/S)	Not Necessary	136.00 FL	*- FL
7	1		*SET HAND GRIP	Not Necessary	68.00 FL	*- FL
8	1		*SIDE MIRROR (N/S)	Cut	128.00 FL	*68.00 FL
9	1		*CLUTCH LEVER	Cut	68.00 FL	*68.00 FL
10	1		*FRONT SIGNAL	Not Necessary	160.00 FL	*- FL
11	1		*SET FAIRING ASSY	Cut	580.00 FL	*480.00 FL
12	1		*FRONT FOOTREST BRACKET	Not Necessary	186.00 FL	*- FL
13	2		*FRONT FOOTREST	Not Necessary	128.00 FL	*- FL
14	1		*GEAR PEDAL	Cut	58.00 FL	*58.00 FL
15	2		*REAR FOOTREST	Not Necessary	80.00 FL	*- FL
16	1		*REAR FOOTREST BRACKET	Not Necessary	178.00 FL	*- FL
17	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
18	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
19	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
20	1		*SET STEERING CONE	Not Necessary	90.00 FS	*- FS
21	1		*REAR BOX	Cut	480.00 FS	*280.00 FS
22	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
23	1		*SET STICKET	Necessary	95.00 FS	*60.00 FS
					Sub Total (\$\$)	3,577.00 1,014.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	260.80 67.40
					Total Parts (\$\$)	3,316.20 946.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO PROVIDE LABOUR	New	420.00	250.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
Gross Labour Cost (S\$)			880.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >