

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 09 May 2023

Preliminary Advice

Insured Vehicle No	: SLP1156B	Accident Date	: 23/10/2022
TP Vehicle No	: FBP4247X	Assignment Date	: 15/02/2023
Make	: YAMAHA SNIPER T150	Est. Duration of Repair	: 3
Date of Inspection	: 16/02/2023		
Inspection At	: EROFIA MOTOR TRADING PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,196.20
Revised Amount	:S\$	1,196.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,196.00
Lump Sum Repair	:S\$	950.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.