

TP ALG.

Hui Rong

# JDM AUTOCARE

1 Kaki Bukit Avenue 6, Blk D #01-51 UEN:UEN53060650W

Contact Person: 9630-3880 (DANIEL)

Estimate for SJK6322E - BMW 318i G20

*REAR BUMPER CLIPS <i>new</i>	\$70.00 <i>30</i>
*REAR BUMPER SIDE RETAINER - L/R <i>new</i>	\$202.55 <i>x.</i>
*REAR BUMPER TOW COVER <i>new</i>	\$46.45 <i>+</i>
*REAR BUMPER REFLECTOR - LH <i>new</i>	\$65.80 <i>+</i>
*REAR BUMPER REFLECTOR GARNISH - LH <i>lit</i>	\$105.60 <i>-</i>
*REAR BUMPER REFLECTOR - RH <i>new</i>	\$65.80 <i>+</i>
*REAR BUMPER REFLECTOR GARNISH - RH <i>new</i>	\$105.60 <i>+</i>
*REAR BUMPER REINFORCEMENT <i>Dented</i>	\$715.25 <i>✓</i>
*REAR BUMPER REVERSE SENSOR SET <i>new</i>	<del>\$960.75</del> <i>-480.</i>
*REAR BUMPER REVERSE SENSOR WIRE <i>new</i>	\$398.15 <i>+</i>
*REAR BUMPER CENTRE ATTACHMENT <i>new</i>	\$241.30 <i>✓</i>
*REAR BUMPER OPENER SWITCH <i>new</i>	\$195.10 <i>+</i>
*REAR BUMPER BOOT ANTENNA <i>new</i>	\$260.80 <i>+</i>
*REAR BUMPER OPENER CONTROL MODULE <i>new Rong</i>	<u>\$780.00</u> <i>380</i>
*REAR BUMPER OPENER SENSOR HOLDER <i>new</i>	\$180.60 <i>+</i>
*REAR BUMPER LOWER DUST COVER (CENTRE) <i>new</i>	\$175.40 <i>+</i>
*TAIL LAMP ASSY - LH <i>new</i>	\$750.60 <i>+</i>
*TAIL LAMP ASSY - RH <i>new</i>	\$750.60 <i>+</i>
*TAILLAMP SEALANT <i>new</i>	\$100.00 <i>+</i>
*TAILLAMP CLIPS <i>new</i>	\$28.00 <i>+</i>
*REAR END PANEL <i>new</i>	\$586.45 <i>+</i>
*REAR END PANEL TOP TRIM <i>new</i>	\$119.50 <i>+</i>
*REAR END PANEL TOP TRIM CLIPS <i>new</i>	\$50.00 <i>+</i>
*BOOTLID <i>Dented</i>	1,580.30 <i>-</i>
*BOOTLID WEATHER STRIPE <i>new</i>	\$169.10 <i>+</i>
*BOOTLID BADGE <i>new</i>	\$75.00 <i>-</i>
*BOOTLID BADGE CLIPS <i>new</i>	\$6.00 <i>-</i>
*BOOTLID LAMP - LH <i>new</i>	\$552.80 <i>+</i>
*BOOTLID LAMP - RH <i>new</i>	\$552.80 <i>+</i>
*BOOTLID OUTER KEYLESS ANTENNA <i>new</i>	\$362.10 <i>+</i>
*REAR EXHAUST SILENCER <i>new</i>	\$1,127.85 <i>+</i>
*EXHAUST SILENCER HOOK <i>new</i>	\$79.60 <i>+</i>
*EXHAUST SILENCER BRACKET <i>new</i>	\$68.15 <i>+</i>
*EXHAUST SILENCER HEATER SHIELD - CENTER <i>new</i>	\$116.85 <i>+</i>
	<hr/>
	\$11,644.85
	\$582.24
	<hr/>
	<b>\$11,062.61</b>

3859.85

3473.86

Less 5%

*REAR BUMPER FASCIA - M Sport <i>Dented.</i>	<del>\$2,500.00</del> <i>1700.</i>
*REAR BUMPER DIFFUSER CENTER - M Sport <i>Dented.</i>	<del>\$2,000.00</del> <i>1800.</i>
*EXHAUST SILENCER CHROME PIPE <i>new</i>	\$480.00 <i>+</i>
*REAR BUMPER SIDE AIR VENT COVER <i>new</i>	\$480.00 <i>+</i>

3500

\$5,460.00

TO TUFF COAT AFFECTED AREAS  
TO RESET AND DECODE ELECTRONIC MODULE SYSTEM  
TO RESPRAY AFFECTED AREAS  
TO REMOVE & REPLACE DAMAGED PARTS, REPAIR BOOT LID COVER  
AND ALIGNED ALL PARTS  
TO REMOVE & REFIT EXHAUST SILENCER  
TO REMOVE & REFIT INTERIOR UPHOLSTERY

~~\$180.00~~ 30.  
~~\$500.00~~ 120.  
~~\$1,500.00~~ 600.  
~~\$1,200.00~~ 600.  
~~\$300.00~~ X-  
~~\$200.00~~ 50.  
\$3,880.00

1400

Total

\$20,402.61

Admin Lj  
L/S 2/102/23.  
05 Days.

total: 8373.86

L/S 6-7K.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: