

ASS. REC. BY: Rome

REF:

6789

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLT 1056K

at Workshop m/s PREMIUM

of 24, BEVOI SECUR

Insured: ALH

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: T3A

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 80K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLT 1056K Yr Regn: 2017 109

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A3 Sedan 1.0 TFSI 1.8 c.c 999

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 88660 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ28V5J1015829

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 12/02/23 D.O.I. 14/02/23

Survey held at PREMIUM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 49K

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / B.I. / F: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
S + RIS:	_____
Photo:	_____
Others:	_____



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0177/2023/AB
DATE : 14-Feb-23
WIP : 63062

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM TECK WEE PATRICK
ADDRESS : BLK 334 UBI AVENUE 1,#04-799
SINGAPORE 400334

TELEPHONE : HP +65 98778421
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700066973
VEHICLE NO : **SLT 1056 K**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 17/10/2017
ENGINE NO : CHZ 549754
CHASSIS NO : WAUZZZ8V5J1015829
MILEAGE : 88,659
DATE IN : 13-Feb-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Feb-23
PLACE OF ACCIDENT : PUNGGOL FLYOVER, SINGAPORE



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 1056 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	250
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,400.00	?
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILTIAE RESPRAY OF LHS FRONT DOOR	S/N \$	280.00	X
5	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY TO FACILITATE RENEWAL OF FRONT SUBFRAME. INSPECT FOR SUSPENSION DAMAGES AND RENEW WHERE NECESSARY.	S/N \$	2,800.00	?
TOTAL LABOUR CHARGES		:	\$	5,190.00



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 1056 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1000
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR.	\$ 3,500.00	1100
8	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 570.00	280
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ <u>13,602.00</u>	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 1056 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>de</i>	1	\$	2,576.00
2	FRONT BUMPER FIXING PARTS <i>?</i>	1	\$	207.00
3	FRONT BUMPER GUIDE SECTION - LH <i>?</i>	1	\$	46.00
4	FRONT BUMPER GRILLE - CENTER <i>X</i>	1	\$	190.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$	606.00
6	FRONT BUMPER CLOSING ELEMENT - LH <i>?</i>	1	\$	337.00
7	FRONT BUMPER TRIM COVER - LH <i>?</i>	1	\$	193.00
8	FRONT WHEEL HOUSING LINER ADAPTER - LH <i>?</i>	1	\$	45.00
9	RADIATOR GRILLE <i>X</i>	1	\$	1,679.00
10	RADIATOR GRILLE CLOSING ELEMENT <i>X</i>	1	\$	223.00
11	FRONT BUMPER AIR GUIDE GRILLE - LH <i>?</i>	1	\$	222.00
12	AIR CONDITIONER STICKER <i>X</i>	1	\$	9.00
13	CAUTION SIGN STICKER <i>X</i>	1	\$	17.00
14	HORN HIGH TONE - LH <i>X</i>	1	\$	225.00
15	FRONT FENDER - LH <i>bt</i>	1	\$	1,012.00
16	FRONT FENDER RIVET <i>h</i>	5	\$	20.00
17	FRONT FENDER ATTACHMENT PARTS <i>?</i>	1	\$	80.00
18	FRONT FENDER BRACKET - LH CENTER <i>bt</i>	1	\$	57.00
19	FRONT FENDER BRACE <i>?</i>	1	\$	114.00
20	FRONT FENDER BRACKET - LH <i>?</i>	1	\$	34.00
SUB TOTAL SPARE PARTS		:	\$	7,892.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 1056 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER - LH <i>de/</i>	1	\$	198.00
22	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>?</i>	1	\$	99.00
23	HEADLIGHT - LH <i>cta/</i>	1		TBC
24	HEADLIGHT POWER MODULE - LH	1	\$	876.00
25	HEADLIGHT HEAT SINK - LH <i>?</i>	1	\$	868.00
26	HEADLIGHT CONTROL UNIT <i>?</i>	1	\$	643.00
27	HEADLIGHT HOSE - LH <i>?</i>	1	\$	99.00
28	LIFT CYLINDER <i>?</i>	1	\$	165.00
29	LIFT CYLINDER HOSE <i>?</i>	1	\$	81.00
30	LIFT CYLINDER PUMP <i>?</i>	1	\$	175.00
31	LIFT CYLINDER WASH WATER RESERVOIR <i>?</i>	1	\$	231.00
32	LIFT CYLINDER WINDSCREEN WASHER SYSTEM PUMP <i>?</i>	1	\$	140.00
33	LOCK CARRIER <i>?</i>	1	\$	854.00
34	READY-MIX COOLANT	6	\$	326.00
35	RADIATOR AIR GUIDE - LH <i>X</i>	1	\$	31.00
36	RADIATOR AIR GUIDE - UPPER CENTRE <i>X</i>	1	\$	20.00
37	FRONT ALUMINIUM RIM - LH <i>sa-</i>	1	\$	1,380.00
38	FRONT ASSEMBLY CARRIER <i>?</i>	1	\$	1,228.00
39	FRONT BONDED RUBBER BUSHES <i>?</i>	1	\$	117.00
40	FRONT LOWER CONTROL ARM - LH <i>?</i>	1	\$	396.00
SUB TOTAL SPARE PARTS		:	\$	7,927.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 1056 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	FRONT WHEEL BEARING HOUSING ?	1	\$ 642.00	
42	FRONT WHEELHUB WITH BEARING ?	1	TBC	
43	FRONT GUIDE JOINT ?	1	\$ 138.00	
44	FRONT COUPLING ROD ?	1	\$ 106.00	
45	FRONT GAS SHOCK ABSORBER ?	1	\$ 291.00	
46	FRONT DRIVE SHAFT - LH ?	1	\$ 1,548.00	
47	FRONT TRACK ROD ?	1	\$ 107.00	
48	FRONT TIE ROD END - LH ?	1	\$ 132.00	
49	FRONT NUMBER PLATE X	S/N	\$ 60.00	
50	SUNDRIES ?		\$ 700.00	
TOTAL SPARE PARTS		:	\$ 19,543.00	
TOTAL LABOUR CHARGES		:	\$ 13,602.00	
GRAND TOTAL		:	\$ 33,145.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Ramal - Hp 90010068
14/02/23 @ P21420
5 days
EXCESS: TBA
Repair
Resy before paint

PLEASE NOTE :
THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 678G

Vehicle Details

Vehicle No.: SLT1056K

Vehicle to be Exported: No

Intended Deregistration Date: 15 Feb 2023

Vehicle Make: AUDI

Vehicle Model: A3 SEDAN 1.0 TFSI S TRONIC (LED)

Primary Colour: Blue

Manufacturing Year: 2017

Engine No.: CHZ549754

Chassis No.: WAUZZZ8V5J1015829

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$24,479.00

Original Registration Date: 17 Oct 2017

First Registration Date: 17 Oct 2017

Transfer Count: 0

Actual ARF Paid: \$16,271.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 16 Oct 2027

PARF Rebate Amount: \$11,389.00

Intended COE Rebate Details

COE Expiry Date: 16 Oct 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$41,761.00

COE Rebate Amount: \$19,499.00

Total Rebate Amount: \$30,888.00

The information contained herein is correct as at 15 Feb 2023

Audi A3 Sedan 1.0A TFSI S-tronic

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$80,888

Depreciation ⓘ

\$15,570 /yr

[View models with similar depre](#)

Reg Date

19-Oct-2017

(4yrs 8mths 3days COE left)

Mileage

53,350 km (10k /yr)

Manufactured ⓘ

2017

Road Tax ⓘ

\$392 /yr

Transmission

Auto

Dereg Value ⓘ

\$30,904 as of today (change)

OMV ⓘ

\$24,475

COE ⓘ

\$41,761

ARF ⓘ

\$16,265

Engine Cap

999 cc

Power

85.0 kW (113 bhp)

Curb Weight ⓘ

1,280 kg

No. of Owners ⓘ

2

Type of Vehicle

Luxury Sedan