



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD  
BLK 1 KAKI BUKIT AVE 6  
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE  
417883  
ON BEHALF OF TAN TING YUAN

Ref: CS/TP23001724/Uny3e2  
Date: 10/04/2023  
Code: TP149

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	<b>Veh. Inspected</b>	SKL 5122E
<b>Policy No.</b>	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	<b>Assign Date</b>	16/02/2023

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ GLC200 (A)	<b>c.c</b>	1991
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	WDC2539422F552989	<b>Colour</b>	GREY
<b>Odometer</b>	89807 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	235/60 R18	GOODYEAR	7 mm
<b>L/H Front Tyre</b>	235/60 R18	GOODYEAR	7 mm
<b>R/H Rear Tyre</b>	235/60 R18	GOODYEAR	7 mm
<b>L/H Rear Tyre</b>	235/60 R18	GOODYEAR	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	14/02/2023	<b>Inspection Date</b>	16/02/2023
<b>Survey held at</b>	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**