

Not Authorized
 21 Days &
 Resurvey After Painting
 4-5 days



ESTIMATE TO REPAIR

VEHICLE NO. : GBA 4022 G
 MAKE : TOYOTA
 MODEL : HIACE MANUAL
 YEAR : 2007
 CHASSIS NO : JTFHT02P600004453

SURVEYOR NAME :
 DATE OF SURVEY :
 TIME OF SURVEY :

DATE : 15-Feb-23
 DATE OF ACCIDENT : 14-Feb-23
 THIRD PARTY REF : PC 63 M
 THIRD PARTY REF : CHINA TAIPING INSURANCE

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear bumper				\$ 481.80
2 pc	Rear bumper retainer				\$ 49.60
1 pc	Rear end panel		\$ 24.80		\$ 363.70
1 pc	Rear end panel garnish				\$ 112.30
1 pc	Tail gate				\$ 2,293.20
1 pc	Tail gate outer garnish				\$ 151.20
1 pc	Tail gate Emblem				\$ 72.20
1 pc	Tail gate lock				\$ 293.50
1 pc	Tail gate rubber				\$ 433.30
	Less 25%				\$ 4,250.80
					\$ 1,062.70
					\$ 3,188.10
1 pc	70km/h sticker	S/N			\$ 15.00
1 pc	Dangerous highly flammable sticker	S/N			\$ 80.00
1 pc	Flammable liquid sticker	S/N			\$ 40.00
1 pc	Rear No plate	S/N			\$ 40.00
1 Set	Rear bumper sensor	S/N			\$ 200.00
	To putty & spray paint				\$ 500.00
	To transfer tail gate fitting				\$ 80.00
	Labour charge				\$ 600.00
TG/ZX	TOTAL				\$ 4,743.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: