

JDM AUTOCARE

1 Kaki Bukit Avenue 6, Blk D #01-51
Contact Person: 9630-3880 (DANIEL)

TP ALG.

Xiao Chun

Estimate for SMR3436H - Mazda CX-5

*REAR DOOR LH *Revised*
*REAR DOOR LH LOCK *Green*
*REAR DOOR WEATHERSTRIP LH

\$1,664.50 ✓
\$325.00 ✓
\$224.00 ✓
\$2,213.50
\$442.70
\$1,770.80

1664.50
1331.60

Less 20%

PANEL BEATING, REMOVAL AND REPLACING PARTS
TO SPRAY PAINT AFFECTED AREA
TUFF COAT
WIRING CHECK
TRANSFER REAR DOOR LH
TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,
RESET MEMORIES TO SPECIFICATION ETC

~~\$400.00~~ 200
~~\$300.00~~ 200
\$50.00 X
~~\$50.00~~ 30
\$80.00 60
\$180.00 X

490

\$1,060.00

Total

\$2,830.80

Admin
1/5 16/02/23.

02 Days

total: 1821.60

1/5: 1450

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: