

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4372A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	503.04	503.04
1	REAR BUMPER LOWER COVER	DENTED	654.96	654.96
1	REAR BUMPER REINFORCEMENT	DENTED	378.32	378.32
1	REAR CENTRE UNDER COVER	MISSING	425.25	425.25
1	REAR BUMPER TOW COVER	SCRATCHED	82.70	82.70
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	BOOTLID EMBLEM STAR	NECESSARY	81.43	81.43
1	BOOTLID EMBLEM PRIUS	NECESSARY	62.14	62.14
1	BOOTLID EMBLEM HYBRID	NECESSARY	62.14	62.14
2	REAR BUMPER SIDE RETAINER LH/RH @\$112.70	NOT NECESSARY	225.40	-
10	REAR BUMPER CLIP @\$2.20	REPEATED	22.00	-
1	BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-629.85	-568.00
			1,889.53	1,703.98
	SPECIAL NETT ITEMS			
1	BOOTLID COMFORT/ TEL NUMBER STICKER (SN)	NECESSARY	60.00	60.00
1	BOOTLID COMFORT BOOKING APP (SN)	NECESSARY	40.00	40.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			285.70	150.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOTLID.		750.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	60.00	-
			1,470.00	1,200.00
	GRAND TOTAL		3,645.23	3,053.98

Report Ref No. NS/INC23001735/Snp3m4





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,450.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC23001735/Snp3m4

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser