

Estimate

LKK AUTO CONSULTANTS PTE LTD Singapore, Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com	Proforma Invoice No:	Date: Feb 16 2023
	TP Reg. No: SKZ2516Z	Insured Reg. No:
	Ticket No: LKK-J000006	Accident Date: Feb 15 2023
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K	Engine No: L15B4025790	
	Policy No: 0	Claim No: MFL2023D0002307
	Customer: Tan Chik Wee Vehicle: HONDA VEZEL MT 2015 Kilometer: 0 Color: WHITE Fuel: PETROL PH: +65 97669626 Email:	

#	Part Name	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	FRONT FENDER LH	Part	1.00	422.70	274.75	147.95	274.76	274.76
2	FRONT FENDER PROTECTOR LH	Part	1.00	180.60	117.39	63.21	117.39	117.39
3	SET FRONT FENDER MUD FLAP LH-COME COMPLETE	Part	1.00	185.30	120.44	64.86	120.45	120.45
4	ROCKER PANEL GARNISH LH	Part	1.00	380.80	247.52	133.28	247.52	247.52
5	FRONT DOOR LH	Part	1.00	892.60	580.19	312.41	580.19	580.19
6	FRONT DOOR BLACK STICKER LH	Part	1.00	45.80	29.77	16.03	29.77	29.77
7	FRONT DOOR LOCK LH	Part	1.00	260.80	169.52	91.28	169.52	169.52
8	FRONT DOOR TRIM LH	Part	1.00	510.00	331.50	178.50	331.50	331.50
9	FRONT DOOR WEATHERSTRIP LH -DOOR	Part	1.00	98.50	64.02	34.48	64.03	64.03
10	FRONT DOOR LOWER WEATHERSTRIP LH - DOOR	Part	1.00	59.30	38.54	20.76	38.55	38.55
11	FRONT DOOR WINDOW REGULATOR LH	Part	1.00	220.60	143.39	77.21	143.39	143.39
12	REAR DOOR LH	Part	1.00	971.30	631.34	339.96	631.35	631.35
13	REAR DOOR BLACK STICKER LH	Part	1.00	41.10	26.71	14.39	26.72	26.72
14	REAR DOOR WEATHERSTRIP LH -DOOR	Part	1.00	98.50	64.02	34.48	64.03	64.03
15	REAR FENDER PROTECTOR LH	Part	1.00	202.10	131.36	70.74	131.37	131.37
16	FRONT SHOCK ABSORBER LH	Part	1.00	387.60	251.94	135.66	251.94	251.94
17	FRONT LOWER ARM LH	Part	1.00	444.80	289.12	155.68	289.12	289.12
18	FRONT KNUCKLE ARM LH	Part	1.00	280.70	182.45	98.25	182.46	182.46
19	FRONT KNUCKLE BEARING LH	Part	1.00	147.90	96.13	51.77	96.14	96.14
20	FRONT TIE ROD LH	Part	1.00	110.80	72.02	38.78	72.02	72.02
21	FRONT TIE ROD END LH	Part	1.00	126.90	82.48	44.42	82.49	82.49
22	FRONT DOOR CHROME PROTECTOR LH	Part	1.00	200.00	130.00	70.00	130.00	130.00
23	FRONT DOOR TRIM CLIPS 1SET LH	Part	1.00	30.00	19.50	10.50	19.50	19.50
24	REAR DOOR CHROME PROTECTOR LH	Part	1.00	200.00	130.00	70.00	130.00	130.00
25	ROCKER PANEL GARNISH CLIPS 1SET LH	Part	1.00	30.00	19.50	10.50	19.50	19.50
26	RIM	Part	1.00	1,000.00	650.00	350.00	650.00	650.00
							Taxable Value	4,893.71
							Discount Total	2,635.10
							Grand Total	4,893.71

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
27	TO PANEL /BEAT/STRAIGHTEN REALIGN ACCIDENT AFFECTED AREAS	Labour	-	1,000.00	656.29	343.71	656.29	656.29
28	TO SPRAY PAINT ON AFFECTED AREAS	Labour	-	800.00	800.00	0.00	800.00	800.00
29	TO TUFF COAT ON AFFECTED AREAS	Labour	-	60.00	60.00	0.00	60.00	60.00
30	TO CONDUCT WIRING CHECK AND REPAIR	Labour	-	30.00	30.00	0.00	30.00	30.00
31	TO REMOVE/REFIX LEFT INTERIOR UPHOLSTERY ,SEAT ,SEAT BELT	Labour	-	40.00	40.00	0.00	40.00	40.00
32	TO REPLACE /TRANSFER LEFT DOOR AND MECHANISM	Labour	-	160.00	160.00	0.00	160.00	160.00
33	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	Labour	-	80.00	80.00	0.00	80.00	80.00
34	TO REPLACE FRONT UNDERCARRIAGE PARTS	Labour	-	180.00	180.00	0.00	180.00	180.00

							Taxable Value	2,006.29
							Discount Total	343.71
							Grand Total	2,006.29

				Parts Total	4,893.71
				Labour Total	2,006.29
				GST Total	0.00
				Grand Total	6,900.00
				Balance	6,900.00

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature