



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref: CS3/GAI23001744/y3

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date: 16/02/2023

Code: GAI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YP 7213Z	Veh. Inspected	SMW 1054M
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000004305	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	15/02/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/02/2023	Inspection Date	17/02/2023
Survey held at	TRI KING AUTO SOLUTIONS PTE LTD 53 UBI AVENUE 1 #01-15 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.